



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-6500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6031 1188



TOYOTA

Steve (LKK)

14/8/24, 4.30pm

00-NJ AL

EXP-?

P/P

ESTIMATE

Account Details ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987				Account No. S1000026 / ICECICS Document No. 0 Document Date 14/08/2024		Customer Details M/s Borneo Motors (Singapore) Pte Ltd 2 Pandan Crescent Inchcape Centre Singapore 128462 Work: 64751288			
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2011	KDH223R	LEPDYQ A1	07/04/2011	PC0224R	0	23251	79/OD/PC0224R		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTFST22P100010078		1KD2077476	60	Ong Wen Hong	--/--/----		0.00	--/--/----	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPB24A00000201 ACC DATE:12/08/2024 TOW/DRIVE IN:DRIVE IN EXCESS: DATE-IN:12/08/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:							50 100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)							100.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P 792 - 2% = 633.60 X 4 dgs = 2534.40							2534.40
4	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS 656 - 2% = 524.80 X 3 = 1574.40							1574.40
5	B	BP-LAB2 TO CHECK WIRING SYSTEM							107.71
6	B	BP-MECH2 TO REMOVE AND REPLACE A/C CONDENSER & RA DIATOR							316.80
7	B	BP-ECU2 TO RESET ECU AND REPROGRAMME							158.40
8	S	BP-SUBLET TO SUPPLY FRONT NUMBER PLATE							80.00
9	1	T52119-26800 COVER, FR BUMPER				1.00	967.80	30.00	677.46
10	2	T53112-26050 GRILLE, RADIATOR, BR				1.00	409.20	30.00	286.44
11	3	T53113-26030 GRILLE, RADIATOR, (H) BR ?				1.00	88.00	30.00	61.60
12	4	T90467-09185 CLIP				10.00	3.90	30.00	27.30
13	5	T52115-26120 SUPPORT, FR BUMPER ?				1.00	269.60	30.00	188.72
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		

Customer Copy



Borneo Motors



TOYOTA

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
17 UBI ROAD 4
SINGAPORE 408611, Tel no.: 6631 1188

ESTIMATE

Account Details	Account No.	Customer Details
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987	S1000026 / ICECICS Document No. 0 Document Date 14/08/2024	M/s Borneo Motors (Singapore) Pte Ltd 2 Pandan Crescent Inchcape Centre Singapore 128462 Work: 64751288

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2011	KDH223R	LEPDYQ A1	07/04/2011	PC0224R	0	23251	79/OD/PC0224R
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTFST22P100010078	1KD2077476	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	6	T52116-26030 SUPPORT, FR BUMPER	1.00	88.50	30.00	61.95
15	7	T52131-26030 REINFORCEMENT, FR	1.00	679.70	30.00	475.79
16	8	T57053-26020 REINFORCE SUB-ASSY,	1.00	269.00	30.00	188.30
17	9	T58127-26040 REINFORCE, FR CROSS	1.00	77.20	30.00	54.04
18	0	T58128-26020 REINFORCE, FR CROSS	1.00	77.20	30.00	54.04
19	1	T52145-26100 STAY, FR BUMPER	1.00	53.40	30.00	37.38
20	2	T52146-26100 STAY, FR BUMPER	1.00	53.40	30.00	37.38
21	3	T53111-26411 GRILLE, RADIATOR	1.00	940.70	30.00	658.49
22	4	T53152-26020 GUIDE, RADIATOR	1.00	228.50	30.00	159.95
23	5	T53301-26090 HOOD SUB-ASSY	1.00	1483.00	30.00	1038.10
24	6	T53801-26011 FENDER SUB-ASSY, FR	1.00	409.30	30.00	286.51
25	7	T53802-26021 FENDER SUB-ASSY, FR	1.00	409.30	30.00	286.51
26	8	T53510-26060 LOCK ASSY, HOOD	1.00	129.90	30.00	90.93
27	9	T53410-26041 HINGE ASSY, HOOD, RH	1.00	81.80	30.00	57.26
28	0	T53420-26041 HINGE ASSY, HOOD, LH	1.00	81.80	30.00	57.26
29	1	T53201-26100 SUPPORT SUB-ASSY, (to upper part) - BT (Dismark photo)	1.00	570.60	30.00	399.42
30	2	T90975-02066 EMBLEM, SYMBOL	1.00	88.70	30.00	62.09
31	3	T81130-26581 UNIT ASSY, HEADLAMP,	1.00	1264.90	30.00	885.43
32	4	T81170-26581 UNIT ASSY, HEADLAMP,	1.00	1264.90	30.00	885.43
33	5	T85315-26100 JAR, X	1.00	96.50	30.00	67.55

For & on behalf of Borneo Motors (Singapore) Pte Ltd	Customer's Signature	Charge Summary	Total 12,057.04
Customer's Signature		Parts 7,085.33 Labour 4,891.71 Sublet 80.00 Lubrication/Fluid 0.00 Others 0.00	GST 9.00% 1,085.13
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company		Less 0.00	Amount Due 13,142.17

Acknowledged by Repairer
Signature:
Date:

Customer Copy