

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/TMI24080206/EVP3E2**Date:** 21/08/2024REFERENCE

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MZD02682
Claimant Vehicle No :	SH8808S	Insured Vehicle No :	YQ3505E
Date of Loss:	13/08/2024	Nature of Claim:	TP
		Claim No:	M2404574

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SH8808S	Engine No:	2ZRS056413
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT TAXI (A)	Chassis No:	JTDKB3FU103561451
Reg. Date:	19/07/2017 (Man. Year: 2017)	Odometer:	595850 km
Colour:	Blue		
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,354.44	918.50	435.94	32.19
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	820.00	680.00	140.00	17.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,186.44	1,610.50	575.94	26.34
Approved Total (Overridden) (S\$)		1,250.00		
(S\$)	2,186.44	1,250.00	936.44	42.83
+ GST 9.00/9.00% (S\$)	196.78	112.50	84.28	42.83
Nett Amount (S\$)	2,383.22	1,362.50	1,020.72	42.83

INSPECTION

Date of Assignment:	14/08/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	14/08/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

Adjuster: CHEN TSUE YEE**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 21 Aug 2024)
Parts:	144	TOYOTA PRIUS HYBRID 1.8 CVT TAXI (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SH8808S)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Broken	503.04 FL	*503.04 FL
2	1		*REAR BUMPER UNDER COVER	Cut	654.96 FL	*654.96 FL
3	1		*REAR BUMPER REINFORCEMENT	Not Necessary	378.32 FL	*- FL
4	10		*REAR BUMPER CLIPS	Not Necessary	22.00 FL	*- FL
5	1		*REVERSE SENSORS	Not Necessary	135.70 F	*- F
6	1		*REAR BUMPER MAT	Necessary	50.00 F	*50.00 F
					Sub Total (\$\$)	1,744.021,208.00
					- List Item Discount on L Items 25.00/25.00% (\$\$)	389.58289.50
					Total Parts (\$\$)	1,354.44918.50

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	400.00	380.00
2	SPRAY PAINTING	New	300.00	280.00
3	R/I REVERSE SENSORS	New	120.00	20.00
Gross Labour Cost (\$)			820.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >