

Not Notarised
11 Aug 2024

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z

AAD2408- 045

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 AUG 2024

SHB9689Z

JTDBK3FU903092349

200303878K

TOYOTA

PRIUS GEN 4

09/08/2024

GBC84398/TH

23/10/2020

PART		LIST	
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	B 1,634.33 ✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	D 243.81 ✓
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	D 123.06 ✓
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	P 369.60 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	S 1,161.83 X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	P 260.51 X
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	M 44.00 ✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	M 19.43 ✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	M 27.62 ✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	R 109.62 X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	R 124.74 X
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	B 1,641.36 ✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	S 243.81 X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	S 493.40 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	S 1,161.83 X
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	S 404.57 X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	R 139.86 X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	R 123.06 X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	S 300.62 X
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	M 55.02 ✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	M 16.91 ✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	M 33.29 ✓
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	S 624.54 X
TOTAL		\$	9,356.82
25%		\$	2,339.21

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z**AAD2408-**

\$	7,017.62
----	-----------------

Special Nett

1	DOOR STICKER TRANSCAB	\$	<i>nn</i>	100.00	<i>6000</i>
1	DOOR STICKER TEL. NO	\$	<i>nn</i>	100.00	<i>6000</i>
1	DOOR TRIM CLIP	\$	<i>nn</i>	75.00	<i>X</i>
1	DOOR WEATHERSTRIP CLIP	\$	<i>nn</i>	80.00	<i>X</i>
1	ROCKER MOULDING CLIP	\$	<i>nn</i>	65.00	<i>X</i>
TOTAL		\$		420.00	

TOTAL PARTS	\$	2,300.00
--------------------	----	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>600</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>nn</i> 380.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>4000</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>1200</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>nn</i> 380.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>5000</i>
To reinstall rear bumper parking sensor.	\$	<i>nn</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>nn</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z**AAD2408-**

To Check Electrical Lighting Concerned.

\$ 170.00 *200*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*

To remove and refit of rear fender fittings, attachment and perform water seepage test.

\$ *nn* 170.00 *X***TOTAL** \$ **5,270.00****Over All Total** \$ **14,587.62****(PART-BY-PART) Repair Days***06 Days**3 days*LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: