

ASS. REC. BY:

REF:

CP TH / 24080209 / Cma3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 03 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHB 96894Yr Regn: 10, 2c

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: ToyC.C. 1798Colour MP White / R

A/C: Insured / Std / NI / NA

Sp. Reading _____

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTDKB31FU903092349Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModl: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wanli

Front

Rear

R/Bal. P mmR/Bal. P mmL/Bal. P mmL/Bal. P mmD.O.A. 9/8/24D.O.I. 14/8/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

o/s body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1 Got BZ, Return Plat18/8 11 Pm @ 3300h Cable

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

☐ : Prel. Report☐ : Final Report

Days Of Repair: _____

Resurvey No. of Trip: _____

Survey Fee: _____

Transportation: _____

S + RS. \$ _____

Fixes _____

Others _____

TOTAL

Report Format :

Lump Sum / I.B.I. (\$) _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech Invs (\$ _____)☐ : Weekend (\$ _____)

Not Notarised
11/11/2024 \$33000

Trans-cab Auto Services Pte Ltd

AAD2408-045

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z

Vehicle No.:

Chassis No.:

UEN No:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

14 AUG 2024

SHB9689Z

JTDKB3FU903092349

200303878K

TOYOTA

PRIUS GEN 4

09/09/2024

GBC84398/TH

23/10/2020

PART		LIST	
1	PANEL SUB-ASSY, REAR DOOR, RH	\$	R1 1,634.33 ✓
1	FRAME SUB-ASSY, REAR DOOR OUTSIDE HANDLE, RH	\$	D11 243.81 ✓
1	HANDLE ASSY, REAR DOOR OUTSIDE, RH	\$	D11 123.06 ✓
1	WEATHERSTRIP, REAR DOOR OPENING TRIM, RH	\$	Sn 369.60 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, REAR RH	\$	Sn 1,161.83 X
1	REGULATOR SUB-ASSY, REAR DOOR WINDOW, RH	\$	Sn 260.51 X
1	TAPE, BLACK OUT, NO.2 REAR RH	\$	M 44.00 ✓
1	TAPE, BLACK OUT, NO.3 REAR RH	\$	M 19.43 ✓
1	TAPE, BLACK OUT, NO.1 REAR RH	\$	M 27.62 ✓
1	HINGE ASSY, REAR DOOR, LOWER RH	\$	R 109.62 X
1	HINGE ASSY, REAR DOOR, UPPER RH	\$	R 124.74 X
1	PANEL SUB-ASSY, FRONT DOOR, RH	\$	R1 1,641.36 ✓
1	FRAME SUB-ASSY, FRONT DOOR OUTSIDE HANDLE, RH	\$	Sn 243.81 X
1	HANDLE ASSY, FRONT DOOR, OUTSIDE RH	\$	Sn 493.40 X
1	MOTOR ASSY, POWER WINDOW REGULATOR, RH	\$	Sn 1,161.83 X
1	WEATHERSTRIP, FRONT DOOR OPENING TRIM, RH	\$	Sn 404.57 X
1	HINGE ASSY, FRONT DOOR, LOWER RH	\$	R 139.86 X
1	HINGE ASSY, FRONT DOOR, UPPER RH	\$	R 123.06 X
1	REGULATOR SUB-ASSY, FRONT DOOR WINDOW, RH	\$	Sn 300.62 X
1	TAPE, BLACK OUT, NO.2 FRT RH	\$	M 55.02 ✓
1	TAPE, BLACK OUT, NO.1 FRT RH	\$	M 16.91 ✓
1	TAPE, BLACK OUT, NO.3 FRT RH	\$	M 33.29 ✓
1	MOULDING ASSY, BODY ROCKER PANEL, RH	\$	Sn 624.54 X
TOTAL		\$	9,356.82
25%		\$	2,339.21

Trans-cab Auto Services Pte Ltd**AAD2408-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z

\$	7,017.62
----	-----------------

Special Nett

1	DOOR STICKER TRANSCAB	\$	<i>na</i>	100.00	<i>60%</i>
1	DOOR STICKER TEL. NO	\$	<i>na</i>	100.00	<i>60%</i>
1	DOOR TRIM CLIP	\$	<i>na</i>	75.00	<i>X</i>
1	DOOR WEATHERSTRIP CLIP	\$	<i>na</i>	80.00	<i>X</i>
1	ROCKER MOULDING CLIP	\$	<i>na</i>	65.00	<i>X</i>

TOTAL	\$	420.00
--------------	----	---------------

TOTAL PARTS	\$	2,300.00
--------------------	----	-----------------

LABOUR

To Rust-Proofing and apply undercoat Of The Affected Areas.	\$	240.00	<i>60%</i>
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	<i>na</i> 380.00	<i>X</i>
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	1,600.00	<i>400%</i>
To transfer of door fittings, attachment and perform water seepage test.	\$	170.00	<i>120%</i>
To transfer of rear end panel fittings, attachment to facilitate bodywork repair.	\$	<i>na</i> 380.00	<i>X</i>
Putty And Spray Painting Of The Affected Portion.	\$	1,600.00	<i>500%</i>
To reinstall rear bumper parking sensor.	\$	<i>na</i> 170.00	<i>X</i>
To transfer of tire, rim and on wheel balancing.	\$	<i>na</i> 170.00	<i>X</i>

Trans-cab Auto Services Pte Ltd**AAD2408-**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHB9689Z

To Check Electrical Lighting Concerned.

\$ 170.00 *201*

To check steering geometry and computer wheel alignment

\$ *nn* 220.00 *X*To remove and refit of rear fender fittings, attachment and
perform water seepage test.\$ *nn* 170.00 *X***TOTAL \$ 5,270.00****Over All Total \$ 14,587.62****(PART-BY-PART) Repair Days***06 Days**3 days*LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHB9689Z
Vehicle to be Exported:	Yes
Intended Deregistration Date:	12 Aug 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)
Primary Colour:	Red
Manufacturing Year:	2020
Engine No.:	2ZR2H06407
Chassis No.:	JTDKB3FU903092349
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,807.00
Original Registration Date:	23 Oct 2020
First Registration Date:	23 Oct 2020
Transfer Count:	0
Actual ARF Paid:	\$14,530.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Oct 2028
PARF Rebate Amount:	\$10,897.00

Intended COE Rebate Details

COE Expiry Date:	22 Oct 2028
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$28,160.00
COE Rebate Amount:	\$14,761.00
Total Rebate Amount:	\$25,658.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 12 Aug 2024

OK