



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CS3/LPC24080210/Kqh3e2
300 BEACH ROAD	Date:	08/10/2024
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

### 1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	SLR 430E	Veh. Inspected	FBL 515U
Policy No.	-	Coverage	0
Claim No.	24/24/24/VP05/029656	Excess	\$0.00
Assign From	CHARMAINE	Assign Date	14/08/2024

### 2. Vehicle Details

Make & Model	HONDA 400X	C.C	399
Engine No.	NC47E1100286	Year of Reg.	13/05/2016
Chassis No.	NC471100333	Colour	RED
Odometer	- KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

### 3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	120/70Z R17	BRIDGESTONE	3
L/H Front Tyre			
R/H Rear Tyre	160/60Z R17	BRIDGESTONE	5
L/H Rear Tyre			

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION AND O/S BODY.

### 5. General Information

Accident Date	06/08/2024	Inspection Date	15/08/2024 (09:54)
Survey held at	SPEEDY MOTOR CYCLE SERVICE CENTRE BLK 10 ANG MO KIO IND.PARK 2A #05-21 SINGAPORE 568047		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

KSC

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.