

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT
DATE:	22-08-24
CLAIM TYPE:	T/P CLAIM
TO:	INCOME
VEHICLE DETAILS	
VEHICLE NO:	SJV4316D
MAKE & MODEL:	TOYOTA WISH
CHASSIS NO:	
ACCIDENT DETAILS	
DATE:	8 August, 2024
TIME:	1720HRS
THIRD PARTY REQUESTOR:	JACK LI

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT FENDER <i>Dented</i>	1	\$ 820.00	\$ 820.00
2	FRONT FENDER INNER COWLING <i>Dented</i>	1	\$ 195.20	\$ 195.20
3	FORNT DOOR <i>Dented</i>	1	\$ 1,355.20	\$ 1,355.20
4	FRONT DOOR HINGE	2	\$ 105.00	\$ 210.00
5	FRONT DOOR CHECKER	1	\$ 155.20	\$ 155.20
6	FRONT DOOR INNER RUBBER	1	\$ 160.00	\$ 160.00
7	FRONT DOOR WEATHERSTRIP	1	\$ 190.00	\$ 190.00
8	FRONT DOOR LOCK <i>Hand</i>	1	\$ 520.00	\$ 520.00
9	FRONT DOOR INNER TRIM BOARD <i>caused</i>	1	\$ 890.00	\$ 890.00
10	FRONT DOOR POWER WINDOW REGULATION <i>Hand</i>	1	\$ 280.00	\$ 280.00
11	FRONT DOOR POWER WINDOW REGULATION MOTOR	1	\$ 450.00	\$ 450.00
12	REAR DOOR <i>Dented</i>	1	\$ 1,205.60	\$ 1,205.60
13	SIDE SKIRT <i>Missing</i>	1	\$ 650.00	\$ 650.00
14	ROCKER PANEL <i>Repair</i>	1	\$ 680.00	\$ 680.00
15	REAR FENDER <i>Repair</i>	1	\$ 980.00	\$ 980.00

TOTAL PRICE \$ 8,741.20

LESS 25% \$ 2,185.30

SUB TOTAL PRICE \$ 6,555.90

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
------	-------------	------	-----------------	------------------

1	FRONT FENDER INNER COWLING CLIPS(SET) <i>new</i>	1	\$ 22.00	\$ 22.00
2	FRONT DOOR INNER TRIM BOARD CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
3	SIDE SKIRT CLIPS(SET) <i>new</i>	1	\$ 20.00	\$ 20.00
4	WHEEL RIM <i>cut</i>	1	\$ 1,000.00	\$ 1,000.00

TOTAL \$ 1,062.00

500

562

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (LH)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 1,400.00	\$ 1,400.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 1,400.00	\$ 1,400.00
3	TUFF COAT	1	\$ 200.00	\$ 200.00
4	WIRING CHECK	1	\$ 80.00	\$ 80.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00
7	REMOVE AND REFIX FRONT DOOR MECHANISM	1	\$ 100.00	\$ 100.00
7	REMOVE AND REFIX REAR DOOR MECHANISM	1	\$ 100.00	\$ 100.00
9	FOUR WHEEL ALIGNMENT	1	\$ 100.00	\$ 100.00

TOTAL \$ 3,660.00

2190

800

1100

60

30

x

60

60

80

ESTIMATE REPORT

TOTAL PARTS COST	\$	7,617.90
TOTAL LABOUR COST	\$	3,660.00
TOTAL REPAIR COST	\$	11,277.90

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin G

2/2 26/08/24

06 days

Resurveyed

20/09/24

sls.

total: 6870.25

4/5: 55K