

WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

not available

merang

14/8/24

2/5 @ 7200

where the Airbag

13 August 2024

5 days

REG NO. : SMX 304 T
MAKE/MODEL : MERCEDES BENZ E220D

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMT(\$)
	<u>LIST ITEMS</u>	
1	Rear boot lid <i>20/3uf</i>	\$ 2770.71 2,950.00 ✓
1	Rear boot chrome moulding <i>slc</i>	\$ 196.00 X
2	Rear boot hinges <i>11</i>	\$ 236.00 X
2	Rear boot lamps <i>11</i>	\$ 1,130.00 X
1	Rear boot inner lock <i>slc</i>	\$ 465.00 X
1	Rear boot logo	\$ 98.00 ✓
1	Rear boot rubber <i>new 7ml</i>	\$ 162.00 ✓
1	Rear boot "AMG" emblem <i>new</i>	\$ 88.00 ✓
2	Rear taillamps <i>new one 0/521</i>	\$ 843 1,686.00 10 C
1	Rear end panel <i>20/3uf</i>	\$ 1006.22 1,248.00 ✓
1	Rear end panel inner garnish <i>7ml</i>	\$ 165.00 ✓
1	Rear bumper <i>20/3uf</i>	\$ 2,094.00 ✓
2	Rear bumper lower brackets <i>11</i>	\$ 90.00 X
1	Rear bumper lower spoiler <i>11</i>	\$ 389.53 655.00 ✓
1	Rear bumper lower chrome moulding <i>one</i>	\$ 342.00 ✓
2	Rear bumper reflectors <i>11</i>	\$ 270.00 X
1	Rear bumper reinforcement <i>slc</i>	\$ 817.00 X
2	Rear bumper side retainers <i>11</i>	\$ 96.00 X
1	Rear bumper centre inner garnish <i>one</i>	\$ 320.21 535.00 ✓
1	Rear bumper tow hook cover <i>11</i>	\$ 45.00 X
2	Rear bumper side brackets <i>11</i>	\$ 144.00 X
6	Rear bumper PDC sensors <i>slc</i>	\$ 1,950.00 X
2	Rear exhaust chrome tail pipes <i>slc</i>	\$ 478.00 X
		\$ 15,940.00
	Less 5%	\$ 797.00
	<i>102</i>	\$ 15,143.00

SPECIAL NETT ITEMS

1	Rear bumper clip (1 set)	mm	\$	100.00	40
1	Rear number plate with holder	11	\$	50.00	X
			\$	150.00	

S/N

LABOUR CHARGES

1	To remove, replaced damaged lamps and check up rear wiring.	\$	80.00	20
2	To remove and refit inner garnishes.	\$	180.00	60
3	To remove and refit rear reverse sensor.	\$	200.00	30
4	To transfer boot lid mechanism and wiring assembly.	\$	120.00	60
5	To apply undercoating.	\$	180.00	50
6	Panel beating.	\$	1,800.00	600
7	To re-spray painting on the affected areas.	\$	1,600.00	800
		\$	4,160.00	

GRAND TOTAL :

\$ 19,453.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-8278-67
102
7400
40
1620
9110.8
22
7200