



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS AUTOMOTIVE ENGRG. & MGT. DIVISION (TP)		Ref:	CS/SPF24080213/Knp3m4	
ACCIDENT CLAIMS SECTION (SPORE POLICE FORCE)		Date:	30/08/2024	
POLICE LOGISTICS BASE (PLB)		Code:	SPF	
1 HEMMANT ROAD SINGAPORE 438675				
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBC 7400T	Veh. Inspected	SNF 7371K	
Policy No.	-	Coverage	0	
Claim No.	ACS/105/009/2024/031 (LK)	Excess	\$0.00	
Assign From	LAI PENG CHONG	Assign Date	14/08/2024	
2. Vehicle Details				
Make & Model	HONDA VEZEL (A)	C.C	1496	
Engine No.	L15Z1005148	Year of Reg.	20/06/2022	
Chassis No.	RV31004323	Colour	METALLIC GREY	
Odometer	33726 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	235/50R18	MICHELIN	9	
L/H Front Tyre	235/50R18	MICHELIN	9	
R/H Rear Tyre	235/50R18	MICHELIN	9	
L/H Rear Tyre	235/50R18	MICHELIN	9	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION.				
DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/07/2024	Inspection Date	20/08/2024	
Survey held at	CAR TIMES AUTOLUTION PTE LTD - 160 SIN MING DRIVE AUTOCITY #02-04, SINGAPORE 575722			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.				
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days				