

MODEL: HONDA VEZEL

VEHICLE NO: SNF7371K
CHASSIS NO: RV3-1004323

DESCRIPTION	REPAIRER'S ESTIMATE(\$)
<u>PARTS (LIST ITEMS)</u>	
FRONT BUMPER <i>841.20</i>	<i>Buc/Red</i> \$ 900.00 ✓
FRONT BUMPER RETAINER LHS	\$ <i>Sn</i> 50.00 ✗
FRONT BUMPER LOWER GRILLE	\$ <i>Red</i> 200.00 ✓
FRONT BUMPER LOWER SPOILER	\$ <i>Red</i> 370.00 ✓
DAYLIGHT LHS	\$ <i>Sn</i> 520.00 ✗
DAYLIGHT GARNISH LHS	\$ <i>mgcm</i> 70.00 ✓
HEADLAMP LHS <i>2180.40</i>	\$ <i>mgcm</i> 2,400.00 ✓
HEADLAMP BRACKET LHS	\$ <i>Sn</i> 70.00 ✗
FRONT GRILLE ASSY <i>1025.10</i>	\$ <i>mgcm</i> 1,050.00 ✗
FRONT GRILLE TOP CHROME	\$ <i>Sn</i> 200.00 ✗
FRONT SENSOR LHS	\$ <i>Sn</i> 350.00 ✗
FRONT REINFORCEMENT	\$ <i>Red</i> 420.00 ✗
FRONT WHEELARCH MOULDING LHS	\$ <i>Sn</i> 280.00 ✗
	\$ 6,880.00
	20% \$ 1,376.00
	\$ 5,504.00
<u>SPECIAL NETT ITEMS</u>	
FRONT BUMPER CLIPS 1 SET	\$ <i>Sn</i> 60.00 ✓
Total	\$ 60.00
TOTAL PARTS	\$ 5,564.00

Not Authorized
61 Rm @ 3600h
Repair After Rain

-3 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/alter spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification is allowed
 - Suppementary parts must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by repairer

Signature

Date:

S/N	DESCRIPTION	REPAIRER'S ESTIMATE (S\$)	
	<u>LABOUR</u>		
1	To remove the affected parts & fittings to commence repairs; replace damaged parts and components	\$ 1,600.00	300/
2	To supply paint materials, expandable items & putty, respray paint on parts replaced & repaired	\$ 1,600.00	220/
3	To remove and re-fix wiring and check all electrical components at damaged areas for proper functions	\$ 100.00	15/
4	To provide anti-rust treatment on affected areas	\$ ~ 100.00	X
5	Dignostic Check	\$ 100.00	60/
6	Remove & refit front sensors	\$ 100.00	60/
	Labour Total :	\$ 3,600.00	
	TOTAL (PARTS & LABOUR):	\$ 9,164.00	