

Note: This document has not been finalised.**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Crystabelle Tan

Date: 28 Aug 2024

Preliminary Advice

Vehicle No	: SNM7361C	Accident Date	: 11/08/2024
Make	: TOYOTA RAV4	Policy No.	: MPC23A00369500
Assignment Date	: 14/08/2024	Excess	: S\$500.00
Date of Inspection	: 14/08/2024	Est. Duration of Repair	: 10
Inspection At	: BORNEO MOTORS (S) PTE LTD (PANDAN) 2 PANDAN CRESCENT SINGAPORE 128462		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	19,576.55 (inclusive supp \$1,607.06)
Revised Amount	:S\$	15,375.72
Check Items (Estimated)	:S\$	0.00
Total	:S\$	15,375.72
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	131,000.00
COE / PARF Rebate	:S\$	46,248.00
Salvage Value	:S\$	
Margin for Repair	:S\$	84,752.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (x) Other comments : Kindly approve on repair cost inclusive supplementary.