



Borneo Motors



TOYOTA

chcpe

o. Reg No. : 196700086Z
ST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details				
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Muhammad Azry Bin Kassim 606D Tampines Street 61 #03-372 Singapore 524606 Mobile: 98555543				
		Document No.					
		0					
		Document Date					
		12/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P2	24/07/2020	SNM7361C	0	32223	79/OD/SNM7361C
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTMY43FV70D042797	M20AV147012	60	Ong Wen Hong	--/--/----	0.00	--/--/----	0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-SUNDRY SUNDRIES POLICY NO.:MPC23A00369500 ACC DATE:11/08/2024 TOW/DRIVE IN:12/08/2024 EXCESS: DATE-IN:12/08/2024 DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORIZED ON:				50	100.00
2	Z	BP-SLANT SUPPLY SEALANT (NETT)				3168	280.00
3	B	BP-LAB2 TO REPLACE AND REPAIR ACCIDENT DAMAGED P @ 72x2				1584	3168.00
4	B	ARTS				2099.20	2099.20
5	B	BP-RES2 TO RESPRAY ALL ACCIDENT AFFECTED AREAS @ 656				107.71	107.71
6	B	BP-LAB2 TO CHECK WIRING SYSTEM				158.40	158.40
7	B	BP-LAB2 TO DRILL HOLE AND INSTALL REVERSE SENSOR				475.20	475.20
8	B	BP-LAB2 TO REMOVE AND TRANSFER BOOT COMPONENT TO NEW BOOT				158.40	158.40
9	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				475.20	475.20
10	S	BP-WS2 TO REMOVE AND INSTALL REAR WINDSCREEN				480.00	480.00
11	S	BP-SUBLET TO SUPPLY SOLAR FILM FOR REAR WINDSCREEN				80.00	80.00
12	1	BP-SUBLET TO SUPPLY REAR NUMBER PLATE 50				336.14	336.14
13	2	T52159-42230 COVER, RR BUMPER de / # 72x2	1.00	480.20	30.00	330.54	330.54
13	2	T52161-42944 PIECE, RR BUMPER, RH # 72x2	1.00	472.20	30.00	330.54	330.54
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle					
			Parts Labour Sublet Lubrication/Fluid Others		Less Amount Due		



Borneo Motors



TOYOTA

ichscape

No. Reg No. : 196700086Z
SST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details		Account No.	Customer Details	
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Muhammad Azry Bin Kassim 606D Tampines Street 61 #03-372 Singapore 524606 Mobile: 98555543	
		Document No. 0		
		Document Date 12/08/2024		

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P2	24/07/2020	SNM7361C	0	32223	79/OD/SNM7361C

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTMY43FV70D042797	M20AV147012	60	Ong Wen Hong	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
14	3	T52162-42944	1.00	472.20	30.00	330.54
15	4	T52453-42040 B0	1.00	901.50	30.00	631.05
16	5	S52161-0K040	10.00	5.80	30.00	40.60
17	6	T52023-42060	1.00	551.50	30.00	386.05
18	7	T52562-42060	1.00	150.50	30.00	105.35
19	8	T52563-42050	1.00	150.50	30.00	105.35
20	9	T67005-42650	1.00	3113.60	30.00	2179.52
21	0	T67881-42070	1.00	465.30	30.00	325.71
22	1	T76802-42140	1.00	332.40	30.00	232.68
23	2	T68105-42300	1.00	1706.50	30.00	1194.55
24	3	T62785-60030	2.00	8.20	30.00	11.48
25	4	T67750-42060 C0	1.00	647.90	30.00	453.53
26	5	T69350-42080	1.00	1100.10	30.00	770.07
27	6	T90975-02070	1.00	79.60	30.00	55.72
28	7	T75431-42180	1.00	75.70	30.00	52.99
29	8	T81551-42230	1.00	748.10	30.00	523.67
30	9	T81561-42230	1.00	748.10	30.00	523.67
31	0	T81581-42092	1.00	672.10	30.00	470.47
32	1	T81591-42121	1.00	352.50	30.00	246.75
33	2	S81910-0K030	1.00	91.80	30.00	64.26

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors



TOYOTA

ichcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no. 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		Mr Muhammad Azry Bin Kassim 606D Tampines Street 61 #03-372 Singapore 524606 Mobile: 98555543			
			Document No. 0					
			Document Date 12/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MXAA52R	ANXGBW P2	24/07/2020	SNM7361C	0	32223	79/OD/SNM7361C	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTMV43FV70D042797		M20AV147012	60	Ong Wen Hong	--/--/----		0.00 --/--/---- 0.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
34	3	S81920-0K010 REFLECTOR ASSY, REFL			1.00	91.80	30.00	64.26
35	4	T58307-42080 PANEL SUB-ASSY, BODY			1.00	1058.90	30.00	741.23
36	5	T21000-20 SIKI 182010 SIKI TACK GO! (BLA			1.00	108.00	30.00	75.60
37	6	T21000-20 SIKI 182010 SIKI TACK GO! (BLA			1.00	108.00	30.00	75.60
38	7	T21000-22 SIKI 207. G+P ADHESIVE PRIMER			1.00	200.00	30.00	140.00
LKK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					<i>Handwritten notes:</i> 7 x 90ml 5 days + 5 = 10 days EXCESS-TBA Revert 14/08/24 Res 50 paint			
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 17,969.49	
			Please acknowledge receipt of vehicle		Parts 10,467.38		GST 9.00% 1,617.25	
					Labour 6,942.11			
					Sublet 560.00			
					Lubrication/Fluid 0.00		Less 0.00	
					Others 0.00		Amount Due 19,586.74	



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z

GST Reg No. : MR-8500000-9

No. 2 PANDAN CRESCENT

SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details		Account No.	Customer Details				
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987		S1000026 / ICECICS	Mr Muhammad Azry Bin Kassim				
		Document No. 0	606D Tampines Street 61 #03-372 Singapore 524606				
		Document Date 26/08/2024	Mobile: 98555543				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	MXAA52R	ANXGBW P2	24/07/2020	SNM7361C	36748	32223	79/OD/SNM7361C
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTM43FV70D042797		M20AV147012	60	Ong Wen Hong	16/08/2024 8.00		26/08/2024 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
13	1	T52159-42230 COVER, RR BUMPER	1.00	480.20	30.00	336.14	
14	2	T52161-42944 PIECE, RR BUMPER, RH	1.00	472.20	30.00	330.54	
15	3	T52453-42040 B0 GUARD, RR BUMPER,	1.00	901.50	30.00	631.05	
16	4	S52161-0K040 PIECE, RR BUMPER	10.00	5.80	30.00	40.60	
17	5	T52023-42060 REINFORCEMENT	1.00	551.50	30.00	386.05	
18	6	T67005-42650 PANEL SUB-ASSY, BACK	1.00	3113.60	30.00	2179.52	
19	7	T76802-42140 GARNISH SUB-ASSY,	1.00	332.40	30.00	232.68	
20	8	T68105-42300 GLASS SUB-ASSY, BACK	1.00	1706.50	30.00	1194.55	
21	9	T75431-42180 EMBLEM, BACK DOOR,	1.00	75.70	30.00	52.99	
22	0	T58307-42080 PANEL SUB-ASSY, BODY	1.00	1058.90	30.00	741.23	
23	1	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	1.00	108.00	30.00	75.60	
24	2	T21000-20 SIKI 182010 SIKI TACK GO! (BLA	1.00	108.00	30.00	75.60	
25	3	T21000-22 SIKI 207. G+P ADHESIVE PRIMER	1.00	200.00	30.00	140.00	
26	4	T89997-30100 ANTENNA, ELECTRICAL <i>short</i>	1.00	100.00	30.00	70.00	
27	5	T64740-42161 C0 PANEL ASSY, DECK <i>ca</i>	1.00	825.10	30.00	577.57	
28	6	T64777-42071 CUSHION, SPARE WHEEL <i>ca</i>	1.00	273.50	30.00	191.45	
29	7	SPC507-42001 RAV4 BACK SENSOR RES <i>short</i>	1.00	221.80	30.00	155.26	
30	8	T89747-30040 BUZZER, WIRELESS <i>short</i>	1.00	187.50	30.00	131.25	
31	9	T75606-42150 MOULDING SUB-ASSY, <i>ca</i>	1.00	154.40	30.00	108.08	
32	0	T58387-42130 C0 PLATE, RR FLOOR <i>bf</i>	1.00	334.70	30.00	234.29	
For & on behalf of		Customer's Signature	Charge Summary		Total		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle	Parts		Less		
			Labour				
			Sublet		Amount Due		
			Lubrication/Fluid				
			Others				

Company Copy



Borneo Motors



TOYOTA

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188

ESTIMATE

Account Details			Account No.		Customer Details			
ECICS Limited 7 Temasek Boulevard #10-01 Suntec Tower One Singapore 038987			S1000026 / ICECICS		Mr Muhammad Azry Bin Kassim 606D Tampines Street 61 #03-372 Singapore 524606 Mobile: 98555543			
			Document No. 0					
			Document Date 26/08/2024					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2020	MXAA52R	ANXGBW P2	24/07/2020	SNM7361C	36748	32223	79/OD/SNM7361C	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTMV43FV70D042797		M20AV147012	60	Ong Wen Hong	16/08/2024 8.00		26/08/2024 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
33	1	T68810-42110 HINGE ASSY, BACK <i>bt</i>			2.00	99.40	30.00	139.16
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 14,875.72	
			Please acknowledge receipt of vehicle		Parts		8,023.61	
					Labour		6,792.11	
					Sublet		560.00	
					Lubrication/Fluid		0.00	
					Others		0.00	
					GST 9.00%		1,338.81	
					Less		0.00	
					Amount Due		16,214.53	

Company Copy