

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2400575

INV Date : 10-09-2024

Reference CS3/SMR24080215/Kqp3m4

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. PC 1966B
Insured Veh. SMB 1598X
Claim No. BUS/08/24/5015
Policy No.
Accident Date 08/08/2024
Inspection Date 03/09/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS STRIDES PREMIER AUTOMOTIVE SERVICES PL. 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		Ref: Date: Code:	CS3/SMR24080215/Kqp3m4 10/09/2024 SMR	
1. Policy Particulars :- PRE-REPAIR SURVEY				
	Insured Veh.	SMB 1598X	Veh. Inspected	PC 1966B
	Policy No.	-	Coverage	0
	Claim No.	BUS/08/24/5015	Excess	\$0.00
	Assign From	HUA YEN	Assign Date	14/08/2024
2. Vehicle Details				
	Make & Model	ISUZU LT134P	C.C	7790
	Engine No.	6HK1602297	Year of Reg.	05/08/2011
	Chassis No.	JALLT134PB7000020	Colour	YELLOW
	Odometer	442313 KM	Steering	IN ORDER
	Brakes	IN ORDER	General	GOOD
	Modification(s)	RIMS: NIL		
3. Conditions of Tyres				
		Size	Make	Balance (mm)
	R/H Front Tyre	11R22.5	GITI	8
	L/H Front Tyre	11R22.5	GITI	8
	R/H Rear Tyre	11R22.5 (D)	GITI	9/9
	L/H Rear Tyre	11R22.5 (D)	GITI	9/9
4. Description of Damages				
THE VEHICLE HAD COMMENCED ITS REPAIR AT THE TIME OF INSPECTION.				
5. General Information				
	Accident Date	08/08/2024	Inspection Date	03/09/2024 (10:46)
	Survey held at	160 SIN MING DRIVE, #01-07 SIN MING AUTO CITY, SINGAPORE 575722 - REPAIRER: INFINITY COACH & TRADING PTE LTD		
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,000-\$4,000				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR: 1 Working Days				

KSC


KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : PC 1966B



PHOTOGRAPHS FOR VEHICLE NO. : PC 1966B



PHOTOGRAPHS FOR VEHICLE NO. : PC 1966B

