

Tropical Tech Automobile Services

BLK 5032 ANG MO KIO AVENUE 3 #01-303 INDUSTRIAL PARK 2 SINGAPORE 569535

TEL : 6481 7773 / 6481 1403 FAX : 6484 4978

E-mail : tsac303@singnet.com.sg

M / s : **AIG Asia Pacific Insurance Pte. Ltd**
78, Shenton Way,
#11-16, Singapore 079120

Attn : Motor Claims Department
Tel : 64193000
Fax : 62256772

Not Notified
21km & 5000p
Runway After Rain
4 days

Final bill : TT 31 / 24 / TP / WT

Registration No : SLM3457K

Make / model : MB E250 (213)

Mileage :

Date : 19/08/2024

TRAFFIC ACCIDENT INVOLVING VEHICLE BEARING REGISTRATION NO: SMK1354K AND SLM3457K ALONG
S33 IPOH LANE CARPARK 13 AUGUST 2024 AT ABOUT 0735HRS.

1pc	Front RH fender				
1pc	Front RH head lamp	3817		\$	1,593.00 ✓
1pc	Front bumper	1949.50		\$	5,139.00 ✓
3pcs	Front bumper parking sensor (RH)		Bucind		2,383.00 ✓
6pcs	Front bumper parking sensor seal ring		(Each \$291.00)	\$	873.00 ✓
1pc	Front bumper side grille (RH)		(Each \$14.00)	\$	84.00 ✓
1pc	Front bumper side grille chrome trimming (RH)			\$	181.00 ✓
1pc	Front bumper side retainer (RH)			\$	153.00 ✓
	Sub total :			\$	42.00 ✓
	Less 10% discount :			\$	10,448.00
	A total :			\$	1,044.80
				\$	9,403.20

Remove & transfer front bumper necessary attachment spare parts item.

Remove and refit front RH fender, front RH head lamp, front bumper, front bumper parking sensors (RH), front bumper parking sensors seal rings, front bumper side grille (RH), front bumper side grille chrome trimming (RH), front bumper side retainer (RH).

To check and refit front head-lamp (RH).

Putty / primer application, spray painting front RH fender, front bumper, front bumper parking sensors (RH).

Grand final amount :

\$	350	600.00
\$	200	100.00
\$	4400	900.00
\$		11,003.20

Tropical Tech Automobile Services


(Authorised Signature)
William Tan

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: