

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SCE 9896K

| Qty | Description of Parts | Condition | Estimate By Workshop (\$)) | Our Adjusted (\$) |
|-----|--|-------------------------|-------------------------------|-------------------|
| | REPLACEMENT OF PARTS | | | |
| 1 | FRONT BUMPER | TO REPAIR SEE LABOUR | 1,436.50 | - |
| 1 | FRONT BUMPER LOWER GRILLE LH | NOT NECESSARY | 81.12 | - |
| 1 | FRONT BUMPER BRACKET LH | NOT NECESSARY | 33.88 | - |
| 1 | FRONT FENDER LH | TO REPAIR SEE LABOUR | 878.84 | - |
| 1 | FRONT HEADLAMP LH | TO REPAIR SEE LABOUR | 3,042.39 | - |
| 2 | FRONT PARKING SENSOR @\$177.45 | NOT NECESSARY | 177.45 | - |
| | LESS 10% DISCOUNT | | -565.02 | - |
| | | | 5,085.16 | - |
| | SPECIAL NETT ITEMS | | | |
| 1 | SUNDRIES (SN) | NECESSARY | 37.50 | 20.00 |
| 10 | FRONT BUMPER CLIPS @\$3.00 (SN) | NOT NECESSARY | 30.00 | - |
| 6 | RIVET @\$4.50 (SN) | NOT NECESSARY | 27.00 | - |
| | | | 94.50 | 20.00 |
| | <u>LABOUR</u> | | | |
| | TO REMOVE AND REFITTING FRONT BUMPER, FRONT FENDER LH AND AECH OTHER. INCLUSIVE OF THE REPAIR OF FRONT BUMPER, FRONT FENDER LH AND FRONT HEADLAMP LH. | | 640.00 | 250.00 |
| | SURFACE PREPARATION, SPRAY PAINT AND POLISH FRONT BUMPER, FRONT FENDER LH AND OTHER AFFECTED AREAS. | | 750.00 | 250.00 |
| | TO PERFORM DIAGNOSTIC CHECK. | NOT NECESSARY | 80.00 | - |
| | HEADLAMP CODING AND ADAPTATION. | NOT NECESSARY | 300.00 | - |
| | | | 1,770.00 | 500.00 |
| | GRAND TOTAL | | 6,949.66 | 520.00 |

Report Ref No. CS/AGI24080219/Rqp3e2(N)



Page No.:2 of 2

| RECOMMENDED COST OF REPAIRS | 520.00 |
|-----------------------------|--------|
| (REPAIR COST NOT CONCLUDE) | |

Report Ref No. CS/AGI24080219/Rqp3e2(N)

MKB

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

X.S.

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M. MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.