

Not Authorised
 61 By @ 3550p

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD829K

AAD2408-039

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

13 AUG 2024

SHD829K

VF1ABL15AUC283425

200303878K

RENAULT

LATITUDE

12/8/2024

PC1991C/ China

29/12/2017

PART	LIST
1 BUMPER COVER REAR	\$ CM 561.70 ✓
1 BUMPER BRACKET CTR REAR	\$ Pn 98.10 X
1 BUMPER BRACKET SIDE LH REAR	\$ Pn 80.80 X
1 BUMPER BRACKET SIDE RH REAR	\$ Pn 82.10 X
1 BUMPER RETAINER LH REAR	\$ Pn 54.20 X
1 BUMPER RETAINER RH REAR	\$ Pn 59.80 ✓
1 BUMPER LOWER REAR	\$ Bn 411.90 ✓
1 BUMPER BEAM REAR	\$ R 547.80 X
1 BUMPER BEAM BRACKET LH REAR	\$ Sn 114.50 X
1 BUMPER BEAM BRACKET RH REAR	\$ Sn 114.50 X
1 BUMPER REFLECTOR LH	\$ Sn 16.60 X
1 BUMPER REFLECTOR RH	\$ Sn 16.60 X
1 BOOT REFLECTOR LAMP LH	\$ Pn 277.70 X
1 BOOT REFLECTOR LAMP RH	\$ Pn 277.70 X
1 TAILLAMP LH	\$ Pn 401.40 X
1 TAILLAMP RH	\$ CM 401.40 ✓
1 FENDER PANEL REAR RH	\$ R 1,933.20 X
1 WHEELARCH REAR RH	\$ Pn 275.40 X
1 OUTER PANEL REAR (End Panel)	\$ R 745.80 X
1 OUTER PANEL REAR (End Panel) TRIM	\$ Pn 404.56 X
1 SPARE WHEEL PANEL	\$ R 1,229.40 X
1 EXHAUST REAR	\$ R 5,263.60 X
1 BOOT REAR	\$ R 1,677.20 ✓
1 BOOT FINISHER	\$ Sn 344.70 X
1 BOOT LOCK	\$ R 246.60 X
1 BOOT WEATHERSTRIP	\$ Sn 178.20 X
1 BOOT STRUT LH	\$ Sn 145.10 X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

AAD2408-039**SHD829K**

- 1 BOOT STRUT RH
- 1 BOOT HINGE LH
- 1 BOOT HINGE RH
- 1 BOOT BADGE 'RENAULT'
- 1 BOOT BADGE

\$	SH	145.10	X
\$	SH	254.20	X
\$	SH	254.20	X
\$	SH	82.40	✓
\$	SH	95.80	✓
TOTAL		\$ 16,792.26	
10%		\$ 1,679.23	
		\$ 15,113.03	

SPECIAL NETT

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 REAR TAIL LAMP CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	SH	700.00	X
\$	SH	65.00	✓
\$	SH	65.00	X
\$	SH	65.00	X
\$	SH	65.00	X
\$	SH	60.00	X
\$	SH	180.00	3012
\$	SH	150.00	X
\$	SH	200.00	X
\$	SH	130.00	X
TOTAL		\$ 1,680.00	
TOTAL PARTS		\$ 16,793.03	

LABOUR

To rust-proofing of the affected areas.

\$ 600.00 301

Putty and spray painting of the affected portion.

\$ 1,200.00 6601

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 2,000.00 5001

To transfer of tailgate fittings and conduct water seepage test.

\$ 170.00 801

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 601

To reinstall rear bumper parking sensor.

\$ 170.00 601

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel Nc Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SHD829K

AAD2408-039

To check steering geometry and computer wheel alignment \$ *nn* 220.00 X

To Transfer Of Fender Fittings, Attachments And Perform
Water Seepage Test.

\$ *nn* 170.00 X
TOTAL \$ 4,910.00

OVERALL TOTAL \$ 21,703.03

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: