



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLN 5315T

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	FRONT BUMPER	DEEP CUT	\$762.80	\$762.80
1	FRONT BUMPER FOG LAMP -LH	CRACKED	\$281.60	\$281.60
1	FRONT BUMPER FOG LAMP COVER	GRAZED	\$110.20	\$110.20
1	FRONT BUMPER SIDE MOULDING -LOWER	DEEP CUT	\$126.20	\$126.20
2	FRONT BUMPER SIDE RETAINERS -R/L @\$48.20	NOT NECESSARY	\$96.40	\$0.00
1	FRONT BUMPER REINFORCEMENT	NOT NECESSARY	\$410.50	\$0.00
1	FRONT FENDER -LH	TO REPAIR SEE LABOUR	\$584.60	\$0.00
1	FRONT HEADLAMP -LH	NOT NECESSARY	\$1,999.80	\$0.00
1	FRONT HEADLAMP LOWER BRACKET	NOT NECESSARY	\$89.60	\$0.00
	LESS 20.00% DISCOUNT		(\$892.34)	(\$256.16)
			\$3,569.36	\$1,024.64

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	SET FRONT BUMPER CLIP (SN)	NECESSARY	\$50.00	\$40.00
			\$50.00	\$40.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK FRONT WIRING		\$40.00	\$20.00
	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS		\$600.00	\$400.00
	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF FRONT FENDER -LH		\$600.00	\$300.00
			\$1,240.00	\$720.00

GRAND TOTAL			\$4,859.36	\$1,784.64
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)			\$1,400.00

Report Ref No: CS/INC24080225/Uqh3

TOTAL FOR SPARE PARTS: \$ 3,619.36 \$ 1,064.64
TOTAL FOR LABOUR : \$ 1,240.00 \$ 720.00
TOTAL REPAIR COST: \$ 4,859.36 \$ 1,784.64



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.