

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

NTUC INCOME INSURANCE CO-OP LTD

1 MARITIME SQUARE

#10-01 HARBOURFONT CENTRE

SINGAPORE 099253

SMW4661R

*Not Authorized
for
merch
15/8/24
2/5 \$1400 /
3 days.
wh. ph. Aturap*

ESTIMATE

VEHICLE NO SLN5315T
MAKE/MODEL HONDA ODYSSEY
ACC DATE 10.08.2024

PARTICULAR		UNIT PRICE	AMOUNT
QTY	LIST PRICE	SS	SS
1	1 FRONT BUMPER <i>Deep cut</i>	762.80	762.80 ✓
2	1 FRONT BUMPER FOG LAMP -LH <i>cra</i>	281.60	281.60 ✓
3	1 FRONT BUMPER FOG LAMP COVER <i>grat</i>	110.20	110.20 ✓
4	1 FRONT BUMPER SIDE MOULDING -LOWER <i>Deep cut</i>	126.20	126.20 ✓
5	2 FRONT BUMPER SIDE RETAINERS -R/L <i>11</i>	48.20	96.40 X
6	1 FRONT BUMPER REINFORCEMENT <i>11</i>	410.50	410.50 X
7	1 FRONT FENDER -LH <i>R</i>	584.60	584.60 X
8	1 FRONT HEADLAMP -LH <i>11</i>	1,999.80	1,999.80 X
9	1 FRONT HEADLAMP LOWER BRACKET <i>11</i>	89.60	89.60 X
			4,461.70
LESS 20%			892.34
			<u>3,569.36</u>

SPECIAL NETT ITEMS:

1	1 (SET) FRONT BUMPER CLIP <i>111</i>		\$ 50.00 <i>40</i>
		TOTAL	<u>\$ 50.00</u>

LABOUR CHARGES :

1	TO CHECK FRONT WIRING	40.00 <i>20</i>
2	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	600.00 <i>400</i>
3	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	600.00 <i>300</i>
		<u>1,240.00</u>

ESTIMATE PARTS AND LABOUR GRAND TOTAL : 4,859.36

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*P. 1280.80
202
1024.64
40
720
1784.64
202
1427.*