

LEANG AUTOMOTIVE  
 BLK 1 KAKI BIKIT AVE 6 #01-68  
 AUTOBAY S'PORE 417883 HP 90286516

Not Available  
 der  
 nears  
 15/8/14  
 2/5 \$2800  
 change H...  
 4 days

VEHICLE No: SML 1550E

1PC	BOOTLID	DO/Buf	\$685.10	—
1PC	BOOTLID REAR LOGO	re	\$38.80	—
1PC	BOOTLID 'CITY' EMBLEM	re	\$35.20	—
1PC	BOOTLID 'IVTEC' EMBLEM	re	\$36.50	—
1PC	BOOTLID OUTER CHROME MOULDING	u	\$366.90	X
2PCS	BOOTLID REFLECTORS @\$425.00	11	\$850.00	X
2PCS	BOOTLID HINGES @\$105.00	11	\$210.00	X
1PC	BOOTLID INNER LOCK	re	\$165.00	X
1PC	BOOTLID LOCK STRICKER	11	\$60.00	X
1PC	BOOTLID WEATHERSTRIP	11	\$166.80	X
1PC	BOOTLID INNER TRIM	11	\$288.90	X
1SET	BOOTLID INNER TRIM CLIPS	11	\$39.00	X
1PC	REAR BUMPER	re/10	\$566.30	—
2PCS	REAR BUMPER SIDE RETAINERS @\$30.00	11	\$60.00	X
1PC	REAR BUMPER LOWER CENTRE GRILLE	10	\$145.80	—
1SET	REAR BUMPER CLIPS	re	\$39.00	—
1PC	REAR END PANEL	DO/Buf	\$445.10	—
1PC	REAR END PANEL TOP GARNISH	7m	\$221.30	—
1PC	REAR FLOOR PANEL	re	\$1,066.30	X
1PC	REAR FLOOR PANEL TOP BOARD	11	\$422.60	X
1PC	REAR BUZZLE SENSOR	11	\$85.00	X
1PC	REAR ANTENNA SENSOR	11	\$105.00	X
			\$6,098.60	

160.00

202

S.NETT

1SET	REAR BUMPER REVERSE SENSOR	malfunction	\$280.00	200
1PC	REAR LICENCE PLATE	11	\$50.00	X
1PC	REAR END PANEL SEALANT	re	\$50.00	30
1SET	REAR FLOOR PANEL INSULATOR	11	\$200.00	X
1PC	REAR WINDSCREEN SEALANT	11	\$50.00	X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00	X

	TO CHECK WIRING		\$50.00	20
	TO DISMANTLE & REPLACED REVERSE SENSOR		\$80.00	30
	TO TRANSFER BOOTLID MECHANISM		\$100.00	50
	TO DISMANTLE & REFIX CUSHION UPHOLSTERY		\$120.00	60

TO DISMANTLE & REFIX REAR WINDSCREEN  
 TO DISMANTLE & REFIX FUEL TANK  
 TO DISMANTLE & REFIX REAR EXHAUST  
 TO SPRAY RUST PROOFING  
 LABOUR FOR PANEL BEATING & REPLACED PARTS  
 TO PUTTY & SPRAY PAINTING

	11	\$120.00	X
	11	\$100.00	X
	11	\$100.00	X
		\$180.00	40
		\$1,000.00	600
		\$1,800.00	750
TOTAL		\$10,428.60	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

1-115260  
 211  
 1712-08  
 230  
 1530  
 350208  
 222  
 2801