

Not Authorized
see notes
15/8/24
1/s \$4500
3 days.



AUTOBACS CAR CARE (SINGAPORE) PTE. LTD.

8 Kaki Bukit Ave 4 #08-40/45/46 Premier@Kaki Bukit S(415875)
Tel : 6702 1555 Fax : 6702 1444
Co. Reg No. : 201500047H GST No. : 201500047H
Email : st.sim@autobacs.com.sg

TO	: NTUC INCOME (SJT2346R)	DATE	: 14-Aug-24
ATTENTION	: MOTOR CLAIMS DEPARTMENT	JOB TYPE	: T/P CLAIMS
OWNER PARTICULAR			
OWNER ID	: SXXXX858Z	P -	_____
		S -	_____
		L -	_____
VEHICLE DETAILS			
VEHICLE NO.	: SMU775H	TOTAL	_____
MODEL / MAKE	: VOLVO XC40	L/S -20%	_____
CHASSIS NO.	: YV1XZACADL2225334	SUB TOTAL	_____
ACCIDENT DETAIL			
DATE	: 9-Aug-24		
TIME	: 08:45 HRS	CONTACT PERSON : MR. SIM 9844 0974	

QUOTATION SUMMARY PAGE 01

CLAIMS DETAIL : PARTS LIST

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	Rear bumper o/s <i>244.60 cur/ton</i>	1	\$ 1,200.00	\$ 1,200.00
2	Rear bumper reinforcement <i>1100.00 D/Surf</i>	1	\$ 2,800.00	\$ 2,800.00
3	Rear bumper outer black cover <i>2167.50 group</i>	1	\$ 3,500.00	\$ 3,500.00
4	Rear bumper diffuser <i>890.90 cur</i>	1	\$ 1,600.00	\$ 1,600.00
TOTAL PRICE				\$ 9100
SUB TOTAL PRICE				\$

QUOTATION SUMMARY PAGE 02

CLAIMS DETAIL : LABOUR CHARGES AND SPRAY PAINTING

TO LABOUR CHARGE FOR REMOVING REAR BUMPER AND REINFORCEMENT TO FACILITATE AND REPLACEMENT OF PARTS	\$ 400.00	✓	
TO RESPRAY REAR BUMPER AND REAR BONNET Tailgate	\$ 500.00	✓	
TO SUPPLY REAR NO. PLATE	\$ 60.00 <i>Surf</i>	405/N	
TOTAL	\$ 900.00		

ESTIMATE REPORT

TOTAL PARTS COST : \$
TOTAL LABOUR COST : \$
TOTAL REPAIR COST : \$

Consultants hence notify the Repairer of the following:
• To resurvey before/after spray painting
• To display damaged parts, before resurvey
• Parts prices are subject to confirmation
• Third party survey is on a "Without Prejudice" basis
• No illegal modification(s) is allowed
• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

2-5003
52
4752-85
40
900
5692-85
202
4884