

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 97800322
LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis : MR053REH104540792
Year of Mfr : 2015
Policy No : 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	BOOTLID <i>DD/ser</i>	1.0	1,294.10	25	970.58
2	BOOTLID HINGE LH <i>11</i>	1.0	94.80	25	71.10
3	BOOTLID HINGE RH <i>11</i>	1.0	94.80	25	71.10
4	BOOTLID INNER TRIMBOARD <i>11</i>	1.0	494.30	25	370.73
5	BOOTLID RUBBER <i>11</i>	1.0	238.20	25	178.65
6	BOOTLID LOCK <i>11</i>	1.0	542.40	25	406.80
7	BOOTLID CABLE	1.0	105.30	25	78.98
8	BOOTLID LAMP RH <i>one</i>	1.0	521.80	25	391.35
9	BOOTLID LAMP LH <i>one</i>	1.0	521.80	25	391.35
10	BOOTLID OUTER CHROME <i>11</i>	1.0	330.80	25	248.10
11	BOOTLID EMBLEM <i>11</i>	1.0	64.90	25	48.68
12	BOOTLID LOGO - COROLLA <i>11</i>	1.0	55.70	25	41.78
13	BOOTLID LOGO - ALTIS <i>11</i>	1.0	62.00	25	46.50
14	BOOTLID LOCK COVER <i>11</i>	1.0		25	
15	BOOTLID LOWER LOCK <i>11</i>	1.0	20.90	25	15.68
16	END PANEL <i>DD</i>	1.0	1,008.40	25	756.30
17	END PANEL TOP GARNISH <i>11</i>	1.0	327.80	25	245.85
18	SPARE TYRE PANEL	1.0	1,222.30	25	916.73
19	SPARE TYRE PANEL TOP TRIMBOARD <i>11</i>	1.0	362.20	25	271.65
20	REAR FLOOR PANEL SIDE PANEL RH <i>11</i>	1.0	37.80	25	28.35
21	REAR FLOOR PANEL SIDE PANEL LH <i>11</i>	1.0	37.80	25	28.35
22	SPARE TYRE SCREW <i>11</i>	1.0	32.90	25	24.68
23	SPARE TYRE BRACKET <i>11</i>	1.0		25	
24	TAIL LAMP RH <i>one</i>	1.0	510.80	25	383.10
25	TAIL LAMP LH <i>11</i>	1.0	510.80	25	383.10
26	TAIL LAMP CLIP RH <i>11</i>	1.0	5.50	25	4.13
27	TAIL LAMP CLIP LH <i>11</i>	1.0	5.50	25	4.13
28	TAIL LAMP PANEL LH <i>11</i>	1.0	151.30	25	113.48
29	TAIL LAMP PANEL RH <i>11</i>	1.0	151.30	25	113.48
30	REAR FENDER LH <i>11</i>	1.0	1,715.20	25	1,286.40
31	REAR FENDER RH <i>11</i>	1.0	1,715.20	25	1,286.40
32	REAR FENDER INNER TRIMBOARD RH <i>11</i>	1.0	447.70	25	335.78
33	REAR FENDER INNER TRIMBOARD LH <i>11</i>	1.0	447.70	25	335.78
34	REAR FENDER INNER AIR DUST RH <i>11</i>	1.0	185.70	25	139.28

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 97800322

LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis: MR053REH104540792
Year of Mfr 2015
Policy No 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
35	REAR FENDER INNER AIR DUST LH 17	1.0	185.70	25	139.28
36	REAR FENDER INNER SHIELD RH 17	1.0	74.80	25	56.10
37	REAR FENDER INNER SHIELD LH 17	1.0	74.80	25	56.10
38	REAR WINDSCREEN MOULDING 17	1.0		25	
39	REAR BUMPER DO 1/2 636.80	1.0	828.80	25	621.60
40	REAR BUMPER RETAINER RH 17	2.0	164.40	25	246.60
41	REAR BUMPER RETAINER LH 17	2.0	164.40	25	246.60
42	REAR BUMPER BRACKET RH 17	1.0		25	
43	REAR BUMPER BRACKET LH 17	1.0		25	
44	REAR BUMPER REINFORCEMENT DO	1.0	598.20	25	448.65
45	REAR BUMPER SPONGE NT	1.0		25	
46	REAR BUMPER REFLECTOR RH 17	1.0	81.80	25	61.35
47	REAR BUMPER REFLECTOR LH 17	1.0	81.80	25	61.35
48	REAR CHASSIS RH 17	1.0		25	
49	REAR CHASSIS LH 17	1.0		25	
50	REAR NUMBER LAMP RH 17	1.0	89.20	25	66.90
51	REAR NUMBER LAMP LH 17	1.0	89.20	25	66.90
52	REAR DOOR RH 17	1.0	1,864.60	25	1,398.45
53	REAR DOOR LH 17	1.0	1,864.60	25	1,398.45
54	REAR FENDER MUDFLAP LH 17	1.0	71.60	25	53.70
55	REAR FENDER MUDFLAP RH 17	1.0	71.60	25	53.70
56	REAR REMOTE CENTER LOCK SENSOR 17	1.0		25	
List Price - Parts Sub Total					14,964.08
57	REAR NUMBER PLATE SUC	1.0	35.00	0	35.00
58	REAR NUMBER PLATE HOLDER SUC	1.0	35.00	0	35.00
59	WINDSCREEN SEALANT 17	2.0	30.00	0	60.00
60	REVERSE CAMERA 17	1.0	650.00	0	650.00
61	REVERSE SENSOR SUC	1.0	350.00	0	350.00
Special Nett Price - Parts Sub Total					1,130.00
Parts Total					16,094.08
62	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	2,500.00	0 800	2,500.00
63	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,800.00	0 900	1,800.00
64	ANTI-RUST COATING	1.0	300.00	0 50	300.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL: 6441 5655 FAX: 6441 5355/6243 8121
R.O.C No: 200104141D GST Reg. No. 20-0104141-D

TO : 97800322
LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis: MR053REH104540792
Year of Mfr 2015
Policy No 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
65	WIRING	1.0	100.00	0	20 100.00
66	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	11 180.00 X
67	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	30 150.00
68	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	200.00	0	60 200.00
69	TO REMOVE & REFIT FUEL TANK	1.0	250.00	0	11 250.00 X
70	FOUR WHEEL ALIGNMENT	1.0	180.00	0	11 180.00 X
Labour 1 Sub Total					5,660.00
<u>LKK Auto Consultants</u> hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
SINGAPORE DOLLARS : TWENTY-THREE THOUSAND SEVEN HUNDRED ELEVEN AND CENTS NINETY-FIVE ONLY			Less Excess		0.00
			SUBTOTAL		21,754.08
			GST 9.00%		1,957.87
			TOTAL		23,711.95

Date of accident : 12/06/2024 11:55 AM. Place : PIE TOWARDS JURONG

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

2-5407.7
257
4015.78
1860
4915.78
33
414