

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 97800322
LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

not Authorized
nkh
mora y
11/7/24
1/5 B4H00/
Echuph. Ate. n
4 days

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis: MR053REH104540792
Year of Mfr 2015
Policy No 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
1	BOOTLID <i>DD/3er</i>	1.0	1,294.10	25	970.58
2	BOOTLID HINGE LH <i>11</i>	1.0	94.80	25	71.10
3	BOOTLID HINGE RH <i>11</i>	1.0	94.80	25	71.10
4	BOOTLID INNER TRIMBOARD <i>11</i>	1.0	494.30	25	370.73
5	BOOTLID RUBBER <i>7m</i>	1.0	238.20	25	178.65
6	BOOTLID LOCK <i>se 11</i>	1.0	542.40	25	406.80
7	BOOTLID CABLE	1.0	105.30	25	78.98
8	BOOTLID LAMP RH <i>one</i>	1.0	521.80	25	391.35
9	BOOTLID LAMP LH <i>one</i>	1.0	521.80	25	391.35
10	BOOTLID OUTER CHROME <i>11</i>	1.0	330.80	25	248.10
11	BOOTLID EMBLEM <i>11</i>	1.0	64.90	25	48.68
12	BOOTLID LOGO - COROLLA <i>11</i>	1.0	55.70	25	41.78
13	BOOTLID LOGO - ALTIS <i>11</i>	1.0	62.00	25	46.50
14	BOOTLID LOCK COVER <i>11</i>	1.0		25	
15	BOOTLID LOWER LOCK <i>11</i>	1.0	20.90	25	15.68
16	END PANEL <i>DD 7m</i>	1.0	1,008.40	25	756.30
17	END PANEL TOP GARNISH <i>11</i>	1.0	327.80	25	245.85
18	SPARE TYRE PANEL	1.0	1,222.30	25	916.73
19	SPARE TYRE PANEL TOP TRIMBOARD <i>11</i>	1.0	362.20	25	271.65
20	REAR FLOOR PANEL SIDE PANEL RH <i>11</i>	1.0	37.80	25	28.35
21	REAR FLOOR PANEL SIDE PANEL LH <i>11</i>	1.0	37.80	25	28.35
22	SPARE TYRE SCREW <i>11</i>	1.0	32.90	25	24.68
23	SPARE TYRE BRACKET <i>11</i>	1.0		25	
24	TAIL LAMP RH <i>one</i>	1.0	510.80	25	383.10
25	TAIL LAMP LH <i>11</i>	1.0	510.80	25	383.10
26	TAIL LAMP CLIP RH <i>11</i>	1.0	5.50	25	4.13
27	TAIL LAMP CLIP LH <i>11</i>	1.0	5.50	25	4.13
28	TAIL LAMP PANEL LH <i>11</i>	1.0	151.30	25	113.48
29	TAIL LAMP PANEL RH <i>11</i>	1.0	151.30	25	113.48
30	REAR FENDER LH <i>11</i>	1.0	1,715.20	25	1,286.40
31	REAR FENDER RH <i>11</i>	1.0	1,715.20	25	1,286.40
32	REAR FENDER INNER TRIMBOARD RH <i>11</i>	1.0	447.70	25	335.78
33	REAR FENDER INNER TRIMBOARD LH <i>11</i>	1.0	447.70	25	335.78
34	REAR FENDER INNER AIR DUST RH <i>11</i>	1.0	185.70	25	139.28

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 97800322
LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis: MR053REH104540792
Year of Mfr 2015
Policy No 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U PRICE	DISC	AMOUNT
35	REAR FENDER INNER AIR DUST LH ¹⁷	1.0	185.70	25	139.28
36	REAR FENDER INNER SHIELD RH ¹⁷	1.0	74.80	25	56.10
37	REAR FENDER INNER SHIELD LH ¹⁷	1.0	74.80	25	56.10
38	REAR WINDSCREEN MOULDING ¹⁷	1.0		25	
39	REAR BUMPER ^{DO 1/2 636.80}	1.0	828.80	25	621.60
40	REAR BUMPER RETAINER RH ¹⁷	2.0	164.40	25	246.60
41	REAR BUMPER RETAINER LH ¹⁷	2.0	164.40	25	246.60
42	REAR BUMPER BRACKET RH ¹⁷	1.0		25	
43	REAR BUMPER BRACKET LH ¹⁷	1.0		25	
44	REAR BUMPER REINFORCEMENT ^{DO}	1.0	598.20	25	448.65
45	REAR BUMPER SPONGE ^{NF}	1.0		25	
46	REAR BUMPER REFLECTOR RH ¹⁷	1.0	81.80	25	61.35
47	REAR BUMPER REFLECTOR LH ¹⁷	1.0	81.80	25	61.35
48	REAR CHASSIS RH ¹⁷	1.0		25	
49	REAR CHASSIS LH ¹⁷	1.0		25	
50	REAR NUMBER LAMP RH ¹⁷	1.0	89.20	25	66.90
51	REAR NUMBER LAMP LH ¹⁷	1.0	89.20	25	66.90
52	REAR DOOR RH ¹⁷	1.0	1,864.60	25	1,398.45
53	REAR DOOR LH ¹⁷	1.0	1,864.60	25	1,398.45
54	REAR FENDER MUDFLAP LH ¹⁷	1.0	71.60	25	53.70
55	REAR FENDER MUDFLAP RH ¹⁷	1.0	71.60	25	53.70
56	REAR REMOTE CENTER LOCK SENSOR ¹⁷	1.0		25	
List Price - Parts Sub Total					14,964.08
57	REAR NUMBER PLATE ^{SVC}	1.0	35.00	0	35.00
58	REAR NUMBER PLATE HOLDER ^{SVC}	1.0	35.00	0	35.00
59	WINDSCREEN SEALANT ¹⁷	2.0	30.00	0	60.00
60	REVERSE CAMERA ¹⁷	1.0	650.00	0	650.00
61	REVERSE SENSOR ^{SVC}	1.0	350.00	0	350.00
Special Nett Price - Parts Sub Total					1,130.00
Parts Total					16,094.08
62	LABOUR TO REMOVE & REFIT NECESSARY PARTS	1.0	2,500.00	0 ⁸⁰⁰	2,500.00
63	SPRAY PAINT ON THE AFFECTED AREAS	1.0	1,800.00	0 ⁹⁰⁰	1,800.00
64	ANTI-RUST COATING	1.0	300.00	0 ⁵⁰	300.00

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

HOCK WAH MOTOR WORKSHOP PTE LTD

BLK 3011 BEDOK INDUSTRIAL PARK E
BEDOK NORTH AVE 4,
#01-2008/10/12/14 SINGAPORE 489977
TEL : 6441 5655 FAX : 6441 5355/6243 8121
R.O.C No : 200104141D GST Reg. No. 20-0104141-D

TO : 97800322
LIM KOK WENG
BLK 237 COMPASSVALE WALK
#12-524
SINGAPORE 540237
TEL : FAX :
PH : 97800322
ATTN :

ESTIMATE BILL

Number : EB00006536
Date : 14/06/2024
Case No : AD00014852
Vehicle No : SBQ2688P
Chassis: MR053REH104540792
Year of Mfr 2015
Policy No 5127506688-01
Model : TOYOTA COROLLA
ALTIS 1.6 A

Term:

Sn	DESCRIPTION	QTY	U_PRICE	DISC	AMOUNT
65	WIRING	1.0	100.00	0	20 100.00
66	TO REMOVE & REFIT WINDSCREEN	1.0	180.00	0	11 180.00 X
67	TO REMOVE & REFIT REVERSE SENSOR	1.0	150.00	0	30 150.00
68	TO REMOVE & REFIT CUSHION & UPHOSTERY	1.0	200.00	0	60 200.00
69	TO REMOVE & REFIT FUEL TANK	1.0	250.00	0	11 250.00 X
70	FOUR WHEEL ALIGNMENT	1.0	180.00	0	11 180.00 Y
Labour 1 Sub Total					5,660.00
SINGAPORE DOLLARS : TWENTY-THREE THOUSAND SEVEN HUNDRED ELEVEN AND CENTS NINETY-FIVE ONLY			Less Excess	0.00	
			SUBTOTAL	21,754.08	
			GST 9.00%	1,957.87	
			TOTAL	23,711.95	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date of accident : 12/06/2024 11:55 AM. Place : PIE TOWARDS JURONG

E. & O. E.

HOCK WAH MOTOR WORKSHOP PTE LTD

CUSTOMER SIGNATURE

AUTHORISED SIGNATURE

* N = Item not subjected to GST

Issued by : Anysia

P-5407.7
252
4055.78
1860
5915.78
322
4141