



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD

INV No. AC2501569

3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV Date 17/03/2025
Reference CD/CTI24080233/Kpa3q2
Code CTI

PROFESSIONAL SERVICE FEE

Vehicle No. SNH 9562C
Insured Veh. YP 9145B
Claim No. SNM24D204618
Policy No. DMCVSNW00042552406
Accident Date 12/08/2024
Inspection Date 15/08/2024

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (9%)	36.00
Grand Total	436.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS CHINA TAIPING INSURANCE (S) PTE LTD	Ref:	CD/CTI24080233/Kpa3q2
3 ANSON ROAD #16-00	Date:	17/03/2025
SPRINGLEAF TOWER SINGAPORE 079909	Code:	CTI

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	YP 9145B	Veh. Inspected	SNH 9562C
Policy No.	DMCVSNW00042552406	Coverage	0
Claim No.	SNM24D204618	Excess	\$0.00
Assign From	CHEE SO CHOW	Assign Date	15/08/2024

2. Vehicle Details

Make & Model	PEUGEOT 3008 1.2 EAT8 ACTIVE PREMIUM	C.C	1199
Engine No.	10TMA30163018	Year of Reg.	13/12/2022
Chassis No.	VF3MRHNSUNS037578	Colour	METALIC GREY
Odometer	66006 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	215/65R17	YOKOHAMA	9
L/H Front Tyre	215/65R17	YOKOHAMA	9
R/H Rear Tyre	215/65R17	YOKOHAMA	9
L/H Rear Tyre	215/65R17	YOKOHAMA	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	12/08/2024	Inspection Date	15/08/2024
Survey held at	OPTIMA WERKZ PTE LTD 10 ANG MO KIO INDUSTRIAL PARK 2A #01-05 AMK AUTOPOINT SINGAPORE 568047		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNH 9562C

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	CUT	\$1,600.00	\$1,500.71
1	REAR BUMPER OUTER MOULDING	MTG CRACKED	\$650.00	\$545.20
2	REAR REVERSE SENSOR	SERVICEABLE	\$720.00	\$0.00
1	REAR BUMPER REINFORCEMENT	BENT	\$900.00	\$785.00
1	REAR BOOT	TO REPAIR SEE LABOUR	\$0.00	\$0.00
	LESS 10.00% DISCOUNT		(\$387.00)	(\$283.09)
			\$3,483.00	\$2,547.82

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER CLIPS	NECESSARY	\$55.00	\$55.00
1	REAR REVERSE SENSOR MOUNTING BRACKET SET	NECESSARY	\$300.00	\$300.00
			\$355.00	\$355.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC.		\$700.00	\$200.00
	LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL & ETC.		\$800.00	\$220.00
	LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC.		\$100.00	\$50.00
	TO CHECK WIRING & ELECTRICAL SYSTEM.		\$100.00	\$0.00
			\$1,700.00	\$470.00

GRAND TOTAL	\$5,538.00	\$3,372.82
--------------------	-------------------	-------------------

RECOMMENDED COST OF REPAIRS		\$3,372.82
------------------------------------	--	-------------------

Report Ref No: CD/CTI24080233/Kpa3q2

KSC

KENNETH KONG SENG CHEONG



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SNH 9562C



PHOTOGRAPHS FOR VEHICLE NO. : SNH 9562C



PHOTOGRAPHS FOR VEHICLE NO. : SNH 9562C



PHOTOGRAPHS FOR VEHICLE NO. : SNH 9562C



PHOTOGRAPHS FOR VEHICLE NO. : SNH 9562C



PHOTOGRAPHS FOR VEHICLE NO. : SNH 9562C

