

Date: 13-8-2024
Vehicle No: SNH9562C
Model: PEUGEOT 3008
Chassis: VF3MRHNSUNS037578
Reg.Year: 13.12.2022

Not with insurance
Repair by paint
2 days
8,3372.82

Third Party Insurer: China Taiping
Third Party Veh No: YP9145B
Date of Accident: 12/8/2024
Estimator: Loong
Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER <i>1500.71</i>	1	<i>Ref / hr</i>	\$1,600.00 ✓
2	REAR BUMPER OUTER MOULDING <i>543.20</i>	1	<i>my car</i>	\$650.00 ✓
3	REAR REVERSE SENSOR	2	\$360.00	\$720.00 X
4	REAR BUMPER REINFORCEMENT <i>785</i>	1		\$900.00 ✓
5	REAR BOOT	1		REPAIR
SUB TOTAL				\$3,870.00
LESS 10%				-\$387.00
PARTS TOTAL				\$3,483.00

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	REAR BUMPER CLIPS	1		\$55.00 ✓
2	REAR REVERSE SENSOR MOUNTING BRACKET SET	1		\$300.00 ✓
S/N TOTAL				\$355.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR & READJUST REAR ACCIDENT AREAS & ETC. *200*

\$700.00

LABOUR CHARGES FOR PAINTING & TO SUPPLY PAINT & FURNISHING MATERIALS AT REAR BOOT, REAR BUMPER, REAR END PANEL & ETC. *220*

\$800.00

LABOUR CHARGES TO REMOVE & REPLACE REAR BUMPER REVERSE SENSOR & ETC. *50*

\$100.00

TO CHECK WIRING & ELECTRICAL SYSTEM. *NA*

\$100.00 X

LABOUR TOTAL \$1,700.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL \$5,538.00

Acknowledged by Repairer

Signature:

Date:

Head office

6 Kung Chong Road Singapore 159143
Tel: (+65) 6472 1313 Fax: (+65) 6472 2112

Branch

9A Serangoon North Ave 5 Singapore 554500
Tel: (+65) 6484 9919 Fax: (+65) 6481 1993

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 Fax: (+65) 6481 1011

