




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
 Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
 Email: alfredauto@hotmail.com

Tyre &
Sports Rim



Reference No.: 120824

[WITHOUT PREJUDICE SAVE AS TO COSTS]

Date: 12.08.2024

Chong Eng Hock

Blk 29 Transit Road #04-20

Singapore 778905.

Honda Vezel

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Estimate Repair Cost for Vehicle Reg. No: SKV 6932 A

1 Pc. Front Bonnet	Bnc		1,180.00	✓	992.30
2 Pcs. Front Bonnet Lock	HT	@ 149.50	299.00	✓	
2 Pcs. Front Bonnet Hinger	reg	@ 129.35	258.70	X	
2 Pcs. Front Bonnet Rubber	src	@ 92.00	184.00	X	
2 Pcs. Front Head Lamp Assy.	broken	@ 749.00	1,498.00	✓	
2 Pcs. Front Head Lamp Bracket	reg	@ 185.00	370.00	X	
2 Pcs. Front Head Lamp HID Bulb	HM	@ 180.00	360.00	X	
1 Pc. Front Grille	broken		530.00	✓	
1 Pc. Front Grille Top Garnish	broken		256.76	✓	
1 Pc. Front Grille Logo	broken Hec		139.30	✓	
8 Pcs. Front Grille Clips	Hec	@ 7.00	56.00	✓	15/- SH
1 Pc. Front Bumper	Reuhl		1,389.00	✓	801.00
1 Pc. Front Bumper Centre Grille	HM		521.38	X	
1 Pc. Front Bumper Lower Grille	defunct/mondy broken		421.88	✓	
2 Pcs. Front Bumper Fog Lamp Assy.	broken	@ 353.30	706.60	✓	
10 Pcs. Front Bumper Fog Lamp Clips	HM	@ 5.00	50.00	X	
10 Pcs. Front Bumper Clips	Hec	@ 6.00	60.00	20/- SH	
2 Pcs. Front Bumper Retainer	HM	@ 128.00	256.00	X	
1 Pc. Front Bumper Lower Pad	HM		378.20	X	
1 Pc. Front Bumper Centre Beam	Reuhl		590.00	✓	345.20
1 Pc. Front Bumper Lower Bracket	HM		323.38	X	
1 Pc. Front Bumper Towing Cover	src		39.10	X	
4 Pcs. Front Bumper Parking Sensor	HF	@ 462.68	1,850.72	X	
4 Pcs. Front Bumper Parking Sensor Holder	HF	@ 30.00	120.00	X	
4 Pcs. Front Bumper Sensor Ring	HF	@ 12.00	48.00	X	
1 Set. Front Bumper Harness Wire	HF		299.00	X	
2 Pcs. Front Fender	reg	@ 585.00	1,170.00	X	
2 Pcs. Front Fender Dust Garnish	HM	@ 199.00	398.00	X	
20 Pcs. Front Fender Dust Garnish Clips	HM	@ 6.00	120.00	X	
2 Pcs. Front Fender Side Round	reg/defunct 0/s HM	@ 258.00	516.00	✓	



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre & Sports Rim



1 Pc. Front Support Panel	<i>Double</i>	1,139.30	✓	598.70
1 Pc. Front Support Centre Beam	<i>HH</i>	884.40	190.00	X
2 Pcs. Rear Fender	<i>Brk</i>	@ 1,351.00	2,702.00	✓ 1768.80
1 Pc. Support Top Garnish	<i>crack</i>		499.00	✓ 218.30
10 Pcs. Support Garnish Clips	<i>gr</i>	@ 6.00	60.00	X
1 Pc. Air Intake Assy.	<i>broken</i>		1,280.00	✓
1 Pc. Air Intake Hose	<i>broken</i>		62.00	✓
1 Pc. Radiator	<i>bt / punctured</i>		916.00	✓
1 Pc. Radiator Top Hose	<i>HH</i>		129.00	X
1 Pc. Radiator Bottom Hose	<i>HH</i>		135.00	X
1 Pc. Radiator Spare Tank	<i>HH</i>		159.00	X
1 Pc. Radiator Fan Assy.	<i>broken</i>		699.00	✓
1 Pc. Air-con Fan Assy.	<i>broken</i>		685.00	✓
2 Pcs. Support Dust Garnish RH/LH	<i>SVC</i>	@ 310.00	620.00	X
1 Pc. Air Scop Housing	<i>HH</i>		230.00	X
1 Pc. Air Filter Hose	<i>HH</i>		210.00	X
2 Pcs. SRS Sensor	<i>HH</i>	@ 310.00	620.00	X
2 Pcs. Fender Round Procter	<i>replaced H/S</i>	@ 305.00	610.00	✓
1 Pc. Rear Windscreen	<i>replaced</i>		1,280.00	X
1 Pc. Rear Windscreen Moulding	<i>HH</i>		330.00	✓ 180/-
1 Set. Rear Windscreen Repair Kit & Sealant	<i>replaced</i>		180.00	X
1 Pc. Front Windscreen	<i>crack</i>		1,390.00	✓
1 Pc. Front Windscreen Moulding	<i>HH HH</i>		350.00	✓ 180/-
1 Set. Front Windscreen Repair Kit & Sealant	<i>HH HH</i>		180.00	✓ 40/- SH
2 Pcs. Rear LH Fender Housing	<i>HH</i>	@ 568.20	1,136.40	X
2 Pcs. Rear LH Fender Dust Garnish	<i>HH</i>	@ 199.20	398.40	X
20 Pcs. Rear Dust Garnish Clips	<i>HH</i>	@ 6.00	120.00	X
1 Pc. Rear Fender Quarter Garnish RH	<i>dislodged</i>		198.40	X ✓
2 Pcs. Rear Fender Inner Garnish Board	<i>dislodged</i>	@ 498.80	997.60	✓
2 Pcs. Rear LH Fender Inner Garnish Holder	<i>HH</i>	@ 350.60	701.20	X
2 Pcs. Rear LH Fender Inner Housing Carpet	<i>HH</i>	@ 330.60	661.20	X
10 Pcs. Rear LH Fender Inner Clips	<i>HH</i>	@ 6.00	60.00	X
1 Pc. Rear Boot	<i>Brk</i>		1,330.40	✓ 1086.60
2 Pcs. Rear Boot Hinger	<i>HH</i>	@ 169.80	339.60	X
2 Pcs. Rear Boot Absorber	<i>SVC</i>	@ 138.20	276.40	X
1 Pc. Rear Boot Inner Garnish	<i>broken</i>		450.30	✓ 385.00
1 Pc. Rear Boot Opener Assy.	<i>SVC</i>		696.40	X
1 Pc. Rear Boot Lock Assy.	<i>HH</i>		249.90	✓
1 Pc. Rear Boot Lock Catch	<i>HH</i>		93.10	X
1 Pc. Rear Boot Weather Slip	<i>dislodged</i>		484.10	✓ 268.30
1 Pc. Rear Windscreen	<i>shattered</i>		982.40	✓




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



BATTERY

1 Set. Rear Windscreen Repair Kit & Sealant <i>HH</i>		280.00	<i>180/- 40/- SH</i>
1 Set. Rear Windscreen Camera Assy. <i>3VL</i>		480.00	X
2 Pcs. Rear Lamp Assy. <i>broken</i>	@ 486.00	972.00	✓
2 Pcs. Rear lamp Housing Panel <i>1yr</i>	@ 428.70	857.40	X
1 Pc. Rear End Panel <i>Bnc</i>		788.60	✓ <i>585.00</i>
2 Pcs. Rear End Panel Base <i>HH</i>	@ 454.70	909.40	X
1 Pc. Rear End Panel Garnish <i>defunct</i>		287.40	✓ <i>185.45</i>
6 Pcs. Rear End Panel Clips <i>HH</i>	@ 10.00	60.00	X
1 Pc. Rear End Panel Centre Holder <i>HH</i>		69.40	X
1 Pc. Rear Spare Tyre Panel <i>Bnc</i>		1,531.00	✓ <i>1130/- to 838.10</i>
1 Pc. Rear Spare Tyre Board <i>defunct</i>		1,239.30	✓ <i>306.60</i>
2 Pcs. Rear Spare Tyre Board Holder <i>HH</i>	@ 310.00	620.00	X
2 Pcs. Rear Spare Tyre RH Corner Panel <i>HH</i>	@ 98.00	196.00	X
1 Pc. Rear Spare Tyre Board Rubber Cover <i>HH</i>		399.10	X
1 Pc. Rear Spare Tyre Lower Dust Cover <i>defunct/broken</i>		568.10	✓ <i>225.10</i>
3 Pcs. Rear Spare Tyre Tube Cofe Floor Mat <i>HH</i>	@ 190.00	570.00	X
1 Pc. Rear Bumper <i>Rein</i>		1,790.50	✓ <i>762.20</i>
1 Pc. Rear Bumper Reinforcement <i>HH</i>		857.40	X
2 Pcs. Rear Bumper Retainer <i>HH</i>	@ 128.60	257.20	X
2 Pcs. Rear Bumper No. Plate Lamp <i>HH</i>	@ 98.00	196.00	X
1 Pc. Rear Bumper Lower Pad <i>HH</i>		396.20	X
1 Pc. Rear Bumper Wire <i>HH</i>		298.50	X
2 4 Pcs. Rear Bumper Parking Sensor <i>Dn</i>	@ 239.60	958.40	<i>220/- SH</i>
4 Pcs. Rear Bumper Parking Sensor Holder <i>HH</i>	@ 29.80	119.20	X
4 Pcs. Rear Bumper Sensor Ring <i>HH</i>	@ 12.00	48.00	X
10 Pcs. Rear Bumper Clips <i>HH</i>	@ 6.00	60.00	<i>20/- SH</i>
2 Pcs. Rear Bumper Lower Dust Garnish <i>HH</i>	@ 238.00	476.00	X
8 Pcs. Rear Bumper Dust Garnish Clips <i>HH</i>	@ 8.00	64.00	X
1 Pc. Rear Exhaust <i>DT</i>		799.80	✓
1 Pc. Rear Exhaust Shield <i>HH</i>		231.40	X
6 Pcs. Rear Exhaust Mounting <i>HH</i>	@ 78.20	469.20	X
1 Pc. Centre Exhaust Pipe <i>HH</i>		696.00	X
1 Pc. Centre Shield Cover <i>HH</i>		199.10	X
2 Pcs. Rear Cushion Assy. <i>3VL</i>	@ 689.20	1,378.40	X
1 Pc. Rear Cushion Lock LH <i>HH</i>		296.50	X
1 Pc. Air-Bag ECU <i>HH</i>		1,890.00	X

Total (Panels / Parts): **59,529.62 (SGD)**

4,674.25



ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



LABOR CHARGES

To remove & refit radiator, pipe, hose, radiator fan & assy. To remove & refit air-con condenser, pipe, Hose & all accident affected area, & top-up gas & oil.	900.00 150/-
To remove & refit front & rear wiring door, interior & all accident affected area.	400.00 60/-
To remove & refit roof lining, interior board, garnish, panel, carpet, cushion & all accident area.	800.00 200/-
To clean & wash all interior & all accident affected area & damaged glass.	280.00 50/-
To remove & refit renew exhaust.	280.00 60/-
To remove & renew front & rear windscreen.	400.00 240/-
To knocking, straightening, welding repair & renew all Accident affected area.	4,500.00 1600/-
To use car frame straightening machine for body & Chassis alignment.	1,200.00 150/-
To respray painting on all accident affected area, inner & outer portion.	2,900.00 1600/-
To rust proof all accident affected area.	500.00 60/-

Total (Labor Charges): 12,160.00 (SGD)

15/08/2024 @ 1040m

Hot Air

2/3mm 18 days

[Signature]

2KK And

Check sign limit.

SM 365.00

Labor 4,170.00

Cost 23,223.79

20% 18,579.03

23,104.03

R/S 10,700/-




ALFRED AUTO

Services & Supplies

Blk 5035 Ang Mo Kio Ave 3 # 01-351 Industrial Park 2 Singapore 569538
Tel: 6483 4586 Fax: 6483 4882 Reg. No. 391089/00-E
Email: alfredauto@hotmail.com

Tyre &
Sports Rim



TOTAL COST SUMMARY

PANELS / PARTS	59,529.62
LABOR CHARGES	12,160.00

Grand Total: **71,689.62 (SGD)**

We shall be glad if you can forward the payment at your early convenience.

ACKNOWLEDGED BY	DATE	ALFRED AUTO SERVICES & SUPPLIES
		<i>Alfred Quah</i>

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.

Payment Method

1. PAYNOW via UEN 39108900E
2. Bank Wire Transfer - (SGD Account)

Beneficiary/Company Name	Alfred Auto Services & Supplies
UEN no.	39108900E
Beneficiary's Bank Name	OCBC Bank
Account No.	620-453233-001
Bank Code	7339
Branch Code	620
Swift Code	OCBCSGSG

Note: Full payment must be completed 7 days from the invoice date. There will be an interest of 1.5% imposed per month on overdue invoice. Thank you.