

MS CAR AUTO PTE LTD

8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @KAKI BUKIT
SINGAPORE 415875

TO	: NTUC	DATE	13/8/2024
VEHICLE NO	: SLT7102X (2017)		
VEHICLE MODEL	: HONDA HRV		Hui Rong
CHASSIS NO	: JHMRU1830GX203257		

PARTS	QTY	PER UNIT	PRICES
1 REAR BUMPER <i>behind</i>	1	\$ 492.50	\$ 492.50 ✓
2 REAR BUMPER SIDE HOLDER <i>new</i>	2	\$ 26.40	\$ 52.80 ✓
3 REAR BUMPER REFLECTOR <i>LH curved</i>	2	\$ 151.80	\$ 303.60 ✓
4 REAR BUMPER UNDERCOVER <i>new</i>	1	\$ 298.40	\$ 298.40 ✓
5 REAR END PANEL <i>new</i>	1	\$ 397.30	\$ 397.30 ✓
6 REAR END PANEL TOP GARNISH <i>behind</i>	1	\$ 98.20	\$ 98.20 ✓
7 REAR END PANEL BUZZER <i>new</i>	1	\$ 87.40	\$ 87.40 ✓
8 REAR END PANEL ANTENNA SENSOR <i>new</i>	1	\$ 98.50	\$ 98.50 ✓
9 TAILLAMP <i>LH cut</i>	2	\$ 489.20	\$ 978.40 ✓
10 TAILLAMP LOWER APRON GARNISH <i>LH torn</i>	2	\$ 195.00	\$ 390.00 ✓
11 TAILGATE <i>Detached</i>	1	\$ 878.90	\$ 878.90 ✓
12 TAILGATE LOCK <i>new</i>	1	\$ 189.40	\$ 189.40 ✓
13 TAILGATE WEATHERSTRIPE <i>new</i>	1	\$ 189.90	\$ 189.90 ✓
14 TAILGATE INNER TRIM BOARD <i>new</i>	1	\$ 250.50	\$ 250.50 ✓
15 TAILGATE REFLECTOR <i>LH cut, RH curved</i>	2	\$ 395.50	\$ 791.00 ✓
16 TAILGATE OUTER GARNISH <i>new</i>	1	\$ 341.20	\$ 341.20 ✓
17 TAILGATE GLASS MOULDING <i>new</i>	1	\$ 112.40	\$ 112.40 ✓
18 SPARE TYRE PANEL TOP COVER <i>new</i>	1	\$ 299.50	\$ 299.50 ✓
19 REAR FENDER INNER TRIM BOARD <i>new</i>	2	\$ 285.00	\$ 570.00 ✓
20 HONDA LOGO <i>new</i>	1	\$ 55.90	\$ 55.90 ✓
21 HRV EMBLEM <i>new</i>	1	\$ 60.40	\$ 60.40 ✓
22 I-VTEC EMBLEM <i>new</i>	1	\$ 62.90	\$ 62.90 ✓
Sub total		SUBTOTAL :	\$ 6,453.80
Less 20%		LESS 20% :	\$ 1,290.75
Total List		PARTS TOTAL :	\$ 5,163.04

SPECIAL NETT	QTY	PER UNIT	PRICES
1 REAR NUMBER PLATE <i>new</i>	1	\$ 30.00	\$ 30.00 ✓
2 REAR NUMBER PLATE HOLDER <i>new</i>	1	\$ 30.00	\$ 30.00 ✓
3 REAR BUMPER CLIPS <i>new</i>	1 SET	\$ 50.00	\$ 50.00 ✓
4 REAR BUMPER UNDERCOVER CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00 ✓
5 REVERSE SENSOR (4 PIECES) <i>new</i>	1 SET	\$ 350.00	\$ 350.00 ✓
6 REAR END PANEL TOP GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00 ✓
7 REAR END PANEL SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00 ✓
8 TAILGATE OUTER GARNISH CLIPS <i>new</i>	1 SET	\$ 20.00	\$ 20.00 ✓
9 TAILGATE INNER TRIM BOARD CLIPS <i>new</i>	1 SET	\$ 30.00	\$ 30.00 ✓
10 TAILGATE GLASS SEALANT <i>new</i>	1 SET	\$ 60.00	\$ 60.00 ✓
11 REAR CAMERA <i>new</i>	1	\$ 480.00	\$ 480.00 ✓

12 REAR FENDER INNER TRIM BOARD CLIPS *Nr 2 SET*

\$ 30.00 \$ 60.00

Sub total S/N TOTAL : \$ 1,220.00

390

LABOUR CHARGES

PRICES

ADJUSTMENT

- 1 PANEL BEATING
- 2 SPRAY PAINTING
- 3 WIRING
- 4 TO SPRAY TUFF COAT
- 5 TO REMOVE REVERSE SENSOR
- 6 TO REMOVE REAR CAMERA
- 7 TO REMOVE UPHOLSTERY
- 8 TO REPLACE TAILGATE GLASS
- 9 TO TRANSFER TAILGATE FITTINGS

\$ 1,200.00 *600*

\$ 1,200.00 *650*

\$ 50.00 *30*

\$ 150.00 *30*

\$ 100.00 *50*

\$ 100.00 *50*

\$ 150.00 *40*

\$ 180.00 *120*

\$ 150.00 *60*

1630

LABOR TOTAL :

\$ 3,280.00

Total: 4989.28

c/s: 4K.

05 Days.

4K.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: