

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CD/III24080238/KMA3Q2

Date: 03/03/2025

REFERENCE

Handling Insurer: India International Insurance Pte Ltd Policy No: D19MFL0000003_05

Claimant Vehicle No : SMS4219G Insured Vehicle No : SH110Z

Date of Loss: 13/08/2024 Nature of Claim: TP Claim No: MFL2024D0010670

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMS4219G

Make & Model: MAZDA 3, 1.5 4DR M-HYBRID ELEGANCE (A) Engine No: P520629192

Reg. Date: 26/02/2020 (Man. Year: 2019) Chassis No: JM6BP2SAAK1101973

Colour: Metallic Silver Odometer: 37204 km

Engine Capacity: 1496 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/45 R18 Rear Tyre Size: 215/45 R18

Front Left Side: Yokohama 9 mm Rear Left Side: Yokohama 9 mm

Front Right Side: Yokohama 9 mm Rear Right Side: Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,883.20	2,278.40	604.80	20.98
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,315.00	935.00	380.00	28.90
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	4,198.20	3,213.40	984.80	23.46
+ GST 9.00/9.00% (S\$)	377.84	289.21	88.63	23.46
Nett Amount (S\$)	4,576.04	3,502.61	1,073.43	23.46
+ Car Rental (4.0 x S\$100.00/day) (S\$)		400.00		
+ Doc/Search Fee (S\$)		2.18		
Nett Liability (S\$)		3,904.79		

INSPECTION

Date of Assignment: 22/08/2024

Date Inspected: 22/08/2024 Inspected At: Alan's United Auto Pte Ltd (HQ)
Blk 7 Sin Ming Industrial Estate, #01-76
Singapore 575642

Estimated Period of Repair: 4.0 days

Adjuster: KENNETH KONG

Manager: Daphne Lee Mooi Ngiuk

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Oct 2024)
Parts:	143	MAZDA 3 1.5 4DR M-HYBRID ELEGANCE (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMS4219G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER FASCIA	Mtg Cracked	995.00 FL	*995.00 FL
2	1		*FRONT N/S BUMPER SIDE RETAINER	Necessary	24.00 FL	*24.00 FL
3	1		*FRONT N/S FENDER	Bent	477.00 FL	*477.00 FL
4	1		*FRONT N/S SPORT RIM	Dented	1,265.00 FL	*1,265.00 FL
5	1		*N/S SIDE MIRROR ASSY	Repair	756.00 FL	*- FL
6	1		*N/S SIDE MIRROR COVER	Dented	87.00 FL	*87.00 FL
					Sub Total (S\$)	3,604.00 2,848.00
					- List Item Discount on L Items 20.00/20.00% (S\$)	720.80 569.60
					Total Parts (S\$)	2,883.20 2,278.40

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TRANSFER SPORT RIM	New	50.00	20.00
2	TO CHECK AND ADJUST WHEEL ALIGNMENT	New	65.00	65.00
3	TO PUTTY AND SPRAY REPLACED PARTS	New	600.00	450.00
4	TO REMOVE ,CUT -OUT DAMAGED PARTS ,PANEL BEATING ,WELDING ,ALIGN ,REFIX AND TO RENEW ABOVE PARTS	New	600.00	400.00
Gross Labour Cost (\$\$)			1,315.00	935.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >