

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SH110Z
Accident Date : 13-Aug-2024

No. : 07139

Date : 14-Aug-2024

Our Ref : 024158 (III) / CHAN

PAGE : 1

TNG ENG LOON
BLK 25 SHELFORD ROAD
#03-02
Singapore 288415

Not Authorized
Putty B4 paint
4 days

ESTIMATED COST OF REPAIR FOR MAZDA 3 SMS4219G

1 pc Front bumper fascia
1 pc Front n/s bumper side retainer
1 pc Front n/s fender
1 pc Front n/s sport rim
1 pc N/s side mirror assy
1 pc N/s side mirror cover

m3cm 995.00 ✓
nu 24.00 —
BM 477.00 —
not 1,265.00 —
R 756.00 ✗
nu 87.00 —

3,604.00

Less 20% : 720.80

2,883.20

To transfer sport rim

50.00 *200*

To check and adjust wheel alignment

65.00 —

To putty and spray replaced parts

600.00 *4500*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *4000*

Total : S\$ 4,198.20

Singapore Dollars Four Thousand One Hundred and
Ninety Eight and Cents Twenty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: