

ASS. REC. BY:

REF:

CD
TII / 24080238 / Kma3

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.Bal. or Market Value: 887K

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 04 days Res.: Yes or NoLum Sum: 1.81 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMS 42196 Yr Regn: 021 20

Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or A1Make: Mazda 3 C.C. 1496Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 37204 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JM6BP2 SAAK1101973Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: _____

R: 215/45R18

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 13/8/24 D.O.I. 22/8/2024

Survey held at _____

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S 1st

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/9 83213.40 Colur

Date/Time, File Pass to?

☐ : Prel. Report☐ : Final Report

1)

Date/Time, File Return to?

Days Of Repair: _____

Resurvey No. of Trlp: _____

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07139

Vehicle Insured : SH110Z
Accident Date : 13-Aug-2024

Date : 14-Aug-2024

Our Ref : 024158 (III) / CHAN

PAGE : 1

TNG ENG LOON
BLK 25 SHELFORD ROAD
#03-02
Singapore 288415

Not Authorized
Returning B4 paint
4 days

ESTIMATED COST OF REPAIR FOR MAZDA 3 SMS4219G

=====

1 pc Front bumper fascia
1 pc Front n/s bumper side retainer
1 pc Front n/s fender
1 pc Front n/s sport rim
1 pc N/s side mirror assy
1 pc N/s side mirror cover

m3cm 995.00 ✓
na 24.00 —
m 477.00 —
na 1,265.00 —
n 756.00 ✗
na 87.00 —

3,604.00

Less 20% : 720.80

2,883.20

To transfer sport rim

50.00 *200*

To check and adjust wheel alignment

65.00 —

To putty and spray replaced parts

600.00 *4500*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

600.00 *4000*

Total : S\$ 4,198.20

=====

Singapore Dollars Four Thousand One Hundred and
Ninety Eight and Cents Twenty Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: