

BMW Dealer

# Performance Motors Limited

A Sime Darby Motors Company  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X  
Toll-Free Number (1800-2255269)

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



*Due 25/8*  
*9/9/24*  
*Survey and repair*

*→ iii*  
*13/8/2024*

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 70841	Page No. : 1 of 5
Date Estimated : 13/08/2024	
Prepared By : Chua Kee Sin	

- ESTIMATE REPAIR FOR - Lu Suat Jin@Loo Suat Jin (Lu XueJun) 30 West Coast Terrace West Coast Gardens Singapore 127239	- ACCOUNT - 40000 Cash Sales - Service Singapore
--	--

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKE2008J	WBA6V120905S54983	28/12/2020	216i Gran Tourer	36727

DESCRIPTION	VALUE
To replace rear bumper include attachment etc and carryout necessary repairing work on accident damage area	<del>850</del> 1,275.00
Painting rear bumper	<del>1,038.00</del>
To check electrical wiring system and lighting at the rear section for proper function.	<del>177.00</del>
Sundries.	<del>40</del> 150.00
<b>Total Labour 1:</b>	<b>2,640.00</b>

DESCRIPTION	QTY	PRIC	VALUE
REAR BUMPER CARRIER <i>? Xan</i>	1	525.75	525.75
SUPPORT <i>? Xan</i>	1	86.70	86.70
RR BUMPER LH INNER SIDE GUIDE <i>? Xan</i>	1	172.60	172.60
RR BUMPER RH INNER SIDE GUIDE <i>? Xan</i>	1	172.60	172.60
LEFT PROTECTION FOIL <i>? Xan</i>	1	12.25	12.25
RIGHT PROTECTION FOIL <i>? Xan</i>	1	12.25	12.25
REAR BUMPER TOWING FLAP EYE PRIMED <i>Xan</i>	1	47.10	47.10
REAR BUMPER TRIM STRIP (BLACK) <i>scu</i>	1	86.75	86.75
REAR BUMPER PANEL PRIMED (LINES PDC <i>repair</i> )	1	1,132.45	1,132.45
DECOUPLING RING PDC TORQUE CONVERTER <i>Xan</i>	4	5.65	22.60
Ultrasonic sensor <i>Xan</i>	4	391.05	1,564.20
<b>Total Parts :</b>			<b>3,835.25</b>