

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

INDIA INTERNATIONAL INSURANCE PTE LTD

64 Cecil Street
IOB Building #04-05
Singapore 049711
Tel: 63476100
Attn: Motor Claim Department

Fax: 62244174 , 62257743

Your Ref No: TP 0824-8194
Claim Type: Third Party
Accident Date: 14 August 2024
TP Veh Reg No: SLT6671B

Estimate No: EST1511654
Date: 15 Aug 2024
Policy No: 1900010776-05
Veh Reg No: SFW121S
Make/Model: TOYOTA CAMRY
HYBRID 2.5G CVT
Chassis No: AXVH701024713
Engine No: A25A0124626
Reg. Date: 24 Jan 2019

Estimate Repair Cost to Vehicle No: SFW121S

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER	729.80	1 PC	729.80	
2 REAR BUMPER SIDE RETAINER - LH/RH	185.50	2 PC	371.00	
3 REAR BUMPER CLIPS	5.50	10 PC	55.00	
4 REAR BUMPER LOWER (BLACK)	524.10	1 PC	524.10	
5 REAR BUMPER REINFORCEMENT	414.90	1 PC	414.90	
6 REAR BUMPER REFLECTOR - LH/RH	81.80	2 PC	163.60	
7 REAR END PANEL	983.20	1 PC	983.20	
8 REAR END PANEL TOP GARNISH	402.70	1 PC	402.70	
9 REAR BOOT	1,705.90	1 PC	1,705.90	
10 REAR BOOT HINGE - LH/RH	287.70	2 PC	575.40	
11 REAR BOOT LAMP - LH/RH	920.70	2 PC	1,841.40	
12 REAR BOOT OUTER GARNISH WITH CAMRY WORDINGS	230.80	1 PC	230.80	
13 REAR BOOT WEATHERSTRIP	264.00	1 PC	264.00	
14 REAR BOOT TOP LOCK	608.60	1 PC	608.60	
15 REAR BOOT LOWER LOCK STRIKER	48.70	1 PC	48.70	
16 REAR BOOT TOYOTA LOGO	97.10	1 PC	97.10	
17 REAR BOOT INNER TRIM	747.30	1 PC	747.30	
18 REAR BOOT INNER TRIM CLIPS	5.50	10 PC	55.00	
19 TAILLAMP - LH/RH	1,331.80	2 PC	2,663.60	
20 TAILLAMP CLIPS - LH/RH	6.50	4 PC	26.00	
21 TAILLAMP PANEL - RH	380.50	1 PC	380.50	
22 REAR FENDER INNER TRIM - LH/RH	699.50	2 PC	1,399.00	
23 SPARE TYRE FLOOR PANEL	1,833.40	1 PC	1,833.40	
24 SPARE TYRE TOP BOARD	702.10	1 PC	702.10	
25 SPARE TYRE TOOLBOX FOAM	577.20	1 PC	577.20	
26 REAR BOOT HYBRID LOGO	79.40	1 PC	79.40	
			17,479.70	
		Less 25%	-4,369.92	13,109.78
Special Net				
27 REAR NUMBER PLATE WITH CASING	35.00	1 PC	35.00	
28 REAR PARKING SENSOR	200.00	1 PC	200.00	
29 REAR PARKING SENSOR	200.00	1 PC	200.00	
30 FLOOR PANEL INSULATOR	250.00	1 PC	250.00	
31 VEHICLE COATING (REFER INVOICE 14JUN2024)	1,000.00	1 PC	1,000.00	
				1,685.00
Labour				
32 TO KNOCK OUT DENTS ON REAR RH FENDER, REAR CHASSIS, CUT/WELD END PANEL, FLOOR PANEL, REMOVE, REPLACE ACCIDENT PORTIONS-	1,600.00	1 JOB	1,600.00	

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

33	TO RESPRAY PAINT ON ACCIDENT PORTIONS-	1,500.00	1 JOB	1,500.00
34	TO CHECK WIRING-	30.00	1 JOB	30.00
35	TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	150.00
36	TO REMOVE, REPLACE REAR BUMPER SENSOR-	80.00	1 JOB	80.00
37	TO TUFFKOTE-	90.00	1 JOB	90.00
38	TO TRANSFER REAR BOOT FITTINGS-	80.00	1 JOB	80.00
				3,530.00

Total	18,324.78
-------	-----------

Add GST @ 9%	1,649.23
--------------	----------

Total Amount Payable SGD	<u>19,974.01</u>
--------------------------	------------------

SINGAPORE DOLLAR NINETEEN THOUSAND NINE HUNDRED SEVENTY FOUR AND CENTS ONE ONLY

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE