

Mitsubishi HC Capital Asia Pacific Pte. Ltd.
Automotive Workshop

No. 8 Fourth Lok Yang Road Singapore 629705
Tel : 64663022 Fax : 68966591
Co. Reg.No. 199400399N GST Reg.No. M2-011899-3

VEHICLE ESTIMATE Dated 14/06/2024

MS FIRST CAPITAL

ACCIDENT DATE : 12/06/2024 13:59hr

VRN : SLC5443P

ATTN: MOTOR CLAIMS DEPT

MODEL : MAZDA 3

YOUR REF : SHB5822G

PARTS REPLACEMENT

	Qty	S\$ Unit	S\$ Amt
1 rear bumper top <i>der 3 der XM</i>	1	\$ 1,120.00	\$ 1,120.00
2 rear bumper lower garnish	1	\$ 1,232.00	\$ 1,232.00 X
3 rear tow cover <i>mis</i>	1	\$ 56.00	\$ 56.00
			\$ 2,408.00
			\$ 481.60
All List -20%			\$ 1,926.40

*1176
202
940.80*

Special Nett

1 bumper clips (set) <i>an</i>	1	\$ 80.00	\$ 80.00 40
2 bumper under cover clips (set) <i>XM</i>	1	\$ 80.00	\$ 80.00 X
3 rear parking sensor (set) <i>X an</i>	1	\$ 580.00	\$ 580.00 X
			\$ 740.00

40

PARTS TOTAL \$ 2,666.40

B. Labour Charges

1 Remove, repair and replace parts for the effected areas.	\$ 650.00 <i>200</i>
2 Spray painting on the effected areas with 2k paint.	\$ 400.00 <i>200</i>
3 Check wiring and ensure proper functioning.	\$ 80.00 <i>X an</i>
4 Remove and reinstall bumper sensors.	\$ 120.00 <i>60</i>

LABOURS TOTAL

\$ 1,250.00 460

Grand Total : \$ 3,916.40
Add 9% GST : \$ 352.48
Nett Total : \$ 4,268.88

No. of repair days: 5

*940.80
40.00
460.00
1440.80*

*RASUL
H/ 9001268
3 day
P/P
16/07/24
Reg by paint*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: