

not Authorized
Kern Grant
telephone: 9696 2064
3 days
21/8/24
2/12/24 4161-70

TRANS EUROKARS PTE LTD
12 Sungei Kadut Ave Singapore 729648

CODE: I0054
CUSTOMER: Great American Insurance Company
ADDRESS: (Singapore Branch)
3 Temasek Avenue
#16-01 Centennial Tower
Singapore 039190

DOCUMENT DATE: 14 Aug 2024
POS OD: MU
PRINTED BY: JESS FRANCIS
SERVICE ADV:
CSP/OP CODE: JESS FRANCIS
DEPT: 1
WIP NO.: XXXXX
REF. NO.: DS/SMX2267D/0133
DATE IN: 12 Aug 2024
EXT. WTY:
MILEAGE: 0

CONTACT NO.: 6827 7888
MODEL: MAZDA6 IPM4 2L SDN EXECUTIVE BLACK LS
CHASSIS NO.: JM6GL1073M0433712
ENGINE NO.: PE21535954
REG NO.: SMX2267D
REGN DATE: 31 Dec 2020

DESCRIPTION:

Item	Description	Qty.	Unit Price	Disc.		Revise amount	Gross amount
				SGD	%	SGD	SGD

NOTES TP CLAIM GAIC 30-7-2024 +

SUB	M6 UBI REPLACE FRT BUMPER, TOP-GRILLE. - PO	792	1.00	0	792	1,584.00
SUB	M6 UBI SPRAY FRT BUMPER, TOP-GRILLE. - PO	945	1.00	0	945	1,890.00
SUB	M6 UBI ELECTRICAL CHECK FOR PROPER FUNCTION. - PO		1.00	0	120	180.00
SUB	M6 UBI REPROGRAM AFTER THE ACCIDENT REPAIRS. - PO		1.00	0	150	200.00
SUB	M6 UBI SUNDRIES. - PO		1.00	0	120	50.00

MGSJ8-50-031 BB	BUMPER,FRONT	De/cu	1.00	1,177.81	0	1,177.81
MGHP9-50-025	GROMMET	1er	2.00	2.36	0	4.72
MBBM4-50-355	RIVETS	1er	4.00	3.71	0	14.84
MGSJ7-50-103	COVER RH,BUMPER INR	11X	1.00	36.50	0	36.50
MGBVG-50-121	PROTECTOR RH,BUMPER CHROME LAMP HOLE	11X	1.00	79.23	0	79.23
MGSJ7-50-101	COVER RH,FRONT BUMP HOLE LAMP	11X	1.00		0	-
MGSJ7-50-7E1 PR	GRILLE,UP. RADIATOR	De/cu	1.00	520.55	0	520.55
MTK21-50-355	RIVETS	1er	6.00	7.42	0	44.52
MS51S-51-833	RIVETS	1er	8.00	3.12	0	24.96
MGSJ7-50-717A	BRACKET,GRILLE-RADIATOR	11X	1.00	114.63	0	114.63
MGSJ7-50-7J0D	MOULD RH,FRONT CHROME	1er	1.00	303.10	0	303.10
MGSJ7-50-151	BRACKET RH,FRT BUMPER CHROME MOULD.	11X	1.00	44.76	0	44.76
MGBVJ-50-719	MESH,GRILLE	11X	1.00	672.35	0	672.35
MEA01-50-037	RIVETS	1er	4.00	7.34	0	29.36
MGSK4-51-031A	UNIT RH,HEADLAMP	3UCX	1.00	5,460.29	0	5,460.29
MGRF5-51-065A	PROTECTOR RH,FRT COMB.	11X	1.00	123.15	0	123.15

MGSJ7-50-153 ~~11X~~ LKK Auto Consultants hence notify the Repairer of the following: bracket RH, front bumper 11X / 14.84 14.84

		Before GST		GST 9%	Total
		Gross	Less: Deposit**		
Parts	8,650.77	12,554.77	-	1,129.93	13,684.70
Surcharge	-	-	-	-	-
Labour	3,904.00	12,554.77	-	1,129.93	13,684.70
Menus	-	-	-	-	-

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for

the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date: _____

Customer signature

Authorised signature