



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SCU 735S

| REPLACEMENT OF PARTS                 |  |                  |                        |                   |
|--------------------------------------|--|------------------|------------------------|-------------------|
| Qty                                  | Description of Parts   | Condition        | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1                                    | TAILGATE   | BENT             | \$1,056.90             | \$1,056.90        |
| 1                                    | SET REAR WINDSCREEN MOULDINGS  | NECESSARY        | \$67.20                | \$67.20           |
| 1                                    | REAR BUMPER  | BUCKLED          | \$881.40               | \$881.40          |
| 1                                    | REAR END PANEL INERN GARNISH   | DENTED           | \$68.80                | \$68.80           |
| 1                                    | TAILGATE WEATHERSTRIP (ADDITIONAL)   | DENTED/DISTORTED | \$128.20               | \$128.20          |
|                                      | <b>LESS 20.00% DISCOUNT</b>  |                  | (\$440.50)             | (\$440.50)        |
|                                      |  |                  | \$1,762.00             | \$1,762.00        |
| Special Nett                         |  |                  |                        |                   |
| Qty                                  | Description of Parts   | Condition        | Workshop Estimate (\$) | Our Adjusted (\$) |
| 1                                    | SEALANT (SN)   | NECESSARY        | \$40.00                | \$40.00           |
|                                      |  |                  | \$40.00                | \$40.00           |
| Labour                               |  |                  |                        |                   |
|                                      | Description of Parts   | Condition        | Workshop Estimate (\$) | Our Adjusted (\$) |
|                                      | TO DISMANTLE+REFIX REAR WINDSCREEN   |                  | \$140.00               | \$120.00          |
|                                      | TO DISMANTLE+REFIX REVERSING CAMERA+REVERSING SENSORS                                  |                  | \$80.00                | \$80.00           |
|                                      | TO DISMANTLE+REFIX REAR FLOOR PANEL CARPET, ETC  |                  | \$80.00                | \$80.00           |
|                                      | TO STRAIGHTEN BODY, TO KNOCK DENTS ON REAR END PANEL, REAR FLOOR PANEL AND RENEW PARTS |                  | \$600.00               | \$550.00          |
|                                      | TO SPRAY PAINT (PEARL WHITE)   |                  | \$800.00               | \$660.00          |
|                                      |  |                  | \$1,700.00             | \$1,490.00        |
| <b>GRAND TOTAL</b>                   |  |                  | <b>\$3,502.00</b>      | <b>\$3,292.00</b> |
|                                      | <b>RECOMMENDED COST OF REPAIRS</b>   |                  |                        | <b>\$3,292.00</b> |
| Report Ref No: CS/AGI24080244/Kqp3m4 |  |                  |                        |                   |

**KSC**

KENNETH KONG SENG CHEONG



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.  
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.