



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 197000288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATION | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
ATTN: MOTOR CLAIMS DEPT

NO. : 47362

- Rev. 1

DATE : 15/08/2024
CLAIM NO. : 12556
POLICY NO. : 5121777941


FROM : RAYMOND

VEHICLE NO. : AK2460Y
MAKE/MODEL : VESPA / SPRINTSPORTS150

(Page 1 of 2)

S/N	Description	Action	Qty	Unit Price	Amount
1	BEADING BODY SHEILD - (REPORTED BY MECHANIC)	REPLACE	1.00	\$388.00	388.00
2	BODY SPRAY PAINT - (REPORTED BY MECHANIC)	Spray	1.00	\$2,500.00	2,500.00
3	HANDLE GRIP - (REPORTED BY MECHANIC)	REPLACE	1.00	\$78.00	78.00
4	KICK STARTER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$155.00	155.00
5	LABOUR P/N: 06766 - LABOUR QUOTED FOR DISMANTLING AND INSTALLATION OF PARTS.	Supply/Install	16.00	\$85.00	1,360.00
6	PLATE NUMBER FRONT (STRAIGHT) P/N: 26249 - (REPORTED BY MECHANIC)	REPLACE	2.00	\$22.00	44.00
7	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951 - (REPORTED BY MECHANIC)	REPLACE	1.00	\$30.00	30.00
8	RUBBER KICK STARTER - (REPORTED BY MECHANIC)	REPLACE	1.00	\$31.00	31.00
9	TRANSPORT CHARGES P/N: 07169 - BIKE TOWED BACK TO BHH		1.00	\$50.00	50.00

*47362 *



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
		SUB TOTAL			\$4,636.00
		GST @ 9 %			\$417.24
		GRAND TOTAL (SGD)			\$5,053.24

50% deposit required before ordering of parts.

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD

Acknowledge & Accepted By



RAYMOND

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

*47362 *



bizSAFE₃

