

ASS. REC. BY:

REF:

C12 / CS/CT124080249/Knh3

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Vsh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \$80k

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 05 days Res.: Yes or NoLum Sum: 1.21 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: STR 1922U Yr Regn: 09, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Traller or (A)Make: M. C180 C.C. 1595Colour: M. Silver A/C: Insured / Std / NI / NASp. Reading: 78596 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WDD2050402R 309420Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: NII / S/Rim / STD / A/Rim or

Tyre Size: F: 225/50R17

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: _____ Rear: _____

R/Bal. 9 mm R/Bal. 9 mmL/Bal. 9 mm L/Bal. 9 mmD.O.A. 10/8/24 D.O.I. 14/8/2024

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

015 157 & UIC

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

1 Wesp said part by part

319 @ 6900.74 Cash (Red. \$7418.56, 51%)

mv \$80k

Date/Time, File Pass to?

☐ : Prel. ReportDays Of Repair: 5

1)

☐ : Final Report

Resurvey No. of Trip: _____

Date/Time, File Return to?

Survey Fee:

Transportation:

S + RS. \$

Fees

Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

Ready Auto Care Pte Ltd - We Care For All Your Car Needs

Blk 10 # 03-06 AMK Auto Point, Ang Mo Kio Ind Park 2A, Ang Mo Kio Ave 5. Singapore 568047
Tel : 64810304 Fax : 64815587 Reg No : 200600989K GST No : 200600989k

China Taiping Insurance (Singapore) Pte Ltd
Motorcar Claim Department
Attn Officer In Charge

Repair Estimate

Not Withheld
Penalty B & Pain Date : 13/8/2024

86900.74

Accident Involving SJR1922U & YQ2287R On 10/08/2024 At AMK Ave 4 Carpark

Car No : SJR1922U

Mercedes C180

5 days

Item	Descriptions	Amount	
1	Front Right Fender	\$ 728.00	✓
2	RH Headlamp	\$ <i>my car</i> 2,295.80	✓
3	RH Headlamp Lower Bracket	\$ <i>CM</i> 226.00	✓
4	Front Right Fender Inne Shield	\$ <i>CM</i> 94.50	✓
5	Front Bumper	<i>Dis</i> \$ <i>my car</i> 1,250.00	✓
6	Front Bumper Inner Center Bracket	\$ <i>CM</i> 223.00	✓
7	Mercedes Logo	\$ <i>me</i> 75.00	✓
8	Front Bumper Center Bracket Aluminium	\$ <i>CM</i> 656.30	✓
9	Front Right Bumper Retainer	\$ <i>CM</i> 32.00	✓
10	Radar Sensor	\$ <i>Sm</i> 1,120.00	✓
11	Bonner Active RH & LH @\$232 X 2	\$ <i>Sm</i> 464.00	✓
12	Front Right Upper Arm	\$ <i>Sm</i> 695.00	✓
13	Front Right Knuckle Arm	\$ <i>Sm</i> 843.20	✓
14	Front Right Shock Absorber	\$ <i>Sm</i> 598.00	✓
15	Front Right Wheel Bearing	\$ <i>nn</i> 455.00	✓
16	Front Right Wheel Cap	\$ <i>od Sm</i> 48.00	✓
17	Front Right Pressure Sensor	\$ <i>Sm</i> 265.50	✓

108

LKK Auto Consultants hence the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Total For Parts (Nett) \$ 10,069.30

S/N Item (s)

- Front Bumper Clips - 1 Set
- Front Right Sport Rim
- King Trolly Towing Service

l-r \$ *nc* 55.00 ✓
\$ *od* 850.00 ✓ *3500*
\$(Bill) 100.00 ✓

Total For S/N \$ 950.00

Labour & Misc

- To Remove All Damaged Parts, Knock Out Dents, Jack Out Damaged Panel Adjust, Replace, Reshape, Cut, Weld, Refix & Realign Body Structure
- Spray Painting For New And Repair Parts Including Supply Of Paints Materials
- Remove & Replace Undecariage Damaged Parts & Tyre Pressure Sensor
- Computerise 4 Wheels Alignment & Balancing
- Computerise Reprogramming Randa Sensor & All False Memory
- Cavity Preservation On All Affected Areas

\$ 1,500.00
\$ 800.00
\$ *nn* 450.00 ✓
\$ 100.00 ✓
\$ *nn* 350.00 ✓
\$ 100.00 ✓

\$ 3,300.00

Ready Auto Care Pte Ltd
Sulynn - 96606551

Total For Parts & Labour \$ 14,319.30

No Of Days For Repair *6 Days*

5 days