

Name & Address:

Motor Claims Department
CHINA TAIPING INSURANCE P/L
 3 ANSON ROAD
 #16-00 SPRINGLEAF TOWER
 SINGAPORE 079909

Vehicle No:

SKU34L

Date:

4-Nov-24

Brand & Model:

Macan

Franchise:

PORSCHE

Email/Fax No:

Contact No:

Chassis/VIN No:

WP1ZZZ95ZJLB06094

Contact Person (Eurokars):

FAIZ

Type of Claim:

THIRD PARTY

YEAR MODEL:

23/02/2018

WIP#:

10778

Contact No (Eurokars):

6331 0680

PARTS / MATERIAL CHARGES

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER	P95B-807-221-A -G2X	1		\$ 1,554.40	\$ 1,554.40
2	FRONT BUMPER LOWER SPOILER	P95B-807-061-S -1E0	1		\$ 349.60	\$ 349.60
3	EXPANSION RIVET	PPAF-038-501- -	16		\$ 44.80	\$ 44.80
4	GRILLE LH	P95B-807-681- -1E0	1		\$ -	\$ 108.60
5	DISC UPPER LH	P95B-807-685- -1E0	1		\$ -	\$ 67.00
6	DISC LOWER LH	P95B-807-877- -1E0	1		\$ -	\$ 58.30
7	GRILLE TRIM LH	P95B-807-819- -1E0	1		\$ 72.10	\$ 72.10
8	SENOSR GASKET	P5Q0-919-133- -9B9	4		\$ 15.60	\$ 15.60
9	AIR DUCT CLOSED LH	P95B-121-333- -1E0	1		\$ -	\$ 84.40
10	FOGLAMP COVER LH	P95B-807-795-B -1E0	1		\$ 46.70	\$ 46.70
11	CROSS MEMBER PEDESTRIAN	P95B-805-241- -	1		\$ -	\$ 290.30
12	FRONT BUMPER SPONGE	P95B-807-550-G -	1		\$ -	\$ 88.30
13	CHARGE AIR COOLER BRACKET LH	P95B-805-295-E -	1		\$ 301.70	\$ 301.70
14	GUIDE PIECE LH	P95B-807-889-C -	1		\$ -	\$ 103.80
15	STRUT BRACE LH	P95B-805-527- -	1		\$ -	\$ 132.20
16	BONNET	P95B-823-031-LY-GRV	1		\$ 5,534.70	\$ 5,534.70
17	GASKET FOR ENGINE COVER	P95B-823-739- -	2		\$ 21.80	\$ 21.80
18	PORSCHE CREST	P9P1-853-601- -	1		\$ 356.50	\$ 356.50
19	DESK PAD CREST	P9P1-853-611- -	1		\$ 21.30	\$ 21.30
20	HOOD BADGE NUT	PWHT-004-974- -	2		\$ 4.60	\$ 4.60
21	HEADLAMP (LEFT)	P95B-941-029-FA-	1		\$ -	\$ 4,185.90
22	ADDITIONAL HEADLAMP LH	P95B-941-181-E -	1		\$ 466.90	\$ 466.90
	SUPPLEMENTARY					
23	ANTIFREEZE PROTECTION	P000-043-305-15-	6		\$ 268.20	\$ 268.20

Sub-Total (Parts Price) \$ 9,058.90 \$ 14,177.70

LABOUR / SERVICES CHARGES

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE BONNET, FRONT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	\$ 3,440.00	\$ 5,160.00
2	TO RESPRAY BONNET, FRONT BUMPER	\$ 2,600.00	\$ 3,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	\$ 150.00	\$ 250.00

4	TO SUPPLY 1 PC CHASSIS STICKER ON BONNET	\$ 150.00	\$ 150.00
5	TO REMOVE & REPLACE CHARGE AIR COOLER BRACKET LH	\$ 780.00	\$ 780.00
6	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	\$ 500.00	\$ 500.00
7	TO TRANSFER THE FRONT BUMPER SENSORS.	\$ 250.00	\$ 500.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.	\$ 150.00	\$ 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	\$ 600.00	\$ 600.00
10	SUNDRIES.	\$ 20.00	\$ 50.00

Survey Date & Time:	Repair Days: 5 Days	Excess:
---------------------	----------------------------	---------

Surveyor Remarks:

Remarks:

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price)	\$ 8,640.00	\$ 11,240.00
	REVISED	PRICE
Parts Price	\$ 9,058.90	\$ 14,177.70
Labour Price	\$ 8,640.00	\$ 11,240.00
Total (Initial Estimate)	\$ 17,698.90	\$ 25,417.70
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ 17,698.90	\$ 25,417.70
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ 17,698.90	\$ 25,417.70
GST 9%	\$ 1,592.90	\$ 2,287.59
GRAND TOTAL	\$ 19,291.80	\$ 27,705.29