

(08/11/13) Wef

ASS. REC. BY:

REF:

CS/CT124080251/Rnh3

8093

**ASSIGNMENT**

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

SKU 34L

at Workshop m/s

ENLAVAND

of

TANJUNGPENANGEN

Insured:

CTI

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Bal. or Market Value:

163K

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SKU 34L

Yr Regn:

2018 / Feb

Type: M.Gar / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

PORSCHE MACAN PDK E6

c.c

1984

Colour

Grey

A/C:

Insured / Std / NI / NA

Sp. Reading

85351

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

WP1222952JLB06094

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

265/40R21

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

01/08/24

D.O.I.

Survey held at

TANJUNGP

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

N/S FR

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

REDAM LIMIT - 92K

We will be advising our principal a cost of repair P/P \$17,698.90 /- with 05 days  
(red, \$7718.8, 30%)

Date/Time, File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

5

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech. Invs (\$

☐

: Weekend (\$

) S + RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I: (\$

TOTAL

Name &amp; Address:

**Motor Claims Department**
**CHINA TAIPING INSURANCE P/L**

3 ANSON ROAD

#16-00 SPRINGLEAF TOWER

SINGAPORE 079909

Email/Fax No:

Contact No:

Vehicle No:

**SKU34L**

Brand &amp; Model:

**Macan**

Chassis/VIN No:

**WP1ZZZ95ZJLB06094**

Date:

**15-Aug-24**

Franchise:

**PORSCHE**

Contact Person (Eurokars):

**FAIZ**

Type of Claim:

**THIRD PARTY**

YEAR MODEL:

**23/02/2018**

WIP#:

**10778**

Contact No (Eurokars):

**6331 0680**
**PARTS / MATERIAL CHARGES**

MARK = Survey Marking [Key "A" if item is approved]

NO	DESCRIPTION	PART NO.	QTY	MARK	REVISED	PRICE
1	FRONT BUMPER <i>SCA /</i>	P95B-807-221-A -G2X	1		-	\$ 1,554.40
2	FRONT BUMPER LOWER SPOILER <i>CA /</i>	P95B-807-061-S -1E0	1		-	\$ 349.60
3	EXPANSION RIVET <i>SCA /</i>	PPAF-038-501- -	16		-	\$ 44.80
4	GRILLE LH <i>?</i>	P95B-807-681- -1E0	1		-	\$ 108.60
5	DISC UPPER LH <i>X</i>	P95B-807-685- -1E0	1		-	\$ 67.00
6	DISC LOWER LH <i>?</i>	P95B-807-877- -1E0	1		-	\$ 58.30
7	GRILLE TRIM LH <i>SCA /</i>	P95B-807-819- -1E0	1		-	\$ 72.10
8	SENO SR GASKET <i>SCA /</i>	P5Q0-919-133- -9B9	4		-	\$ 15.60
9	AIR DUCT CLOSED LH <i>?</i>	P95B-121-333- -1E0	1		-	\$ 84.40
10	FOGLAMP COVER LH <i>SCA /</i>	P95B-807-795-B -1E0	1		-	\$ 46.70
11	CROSS MEMBER PEDESTRIAN <i>?</i>	P95B-805-241- -	1		-	\$ 290.30
12	FRONT BUMPER SPONGE <i>?</i>	P95B-807-550-G -	1		-	\$ 88.30
13	CHARGE AIR COOLER BRACKET LH <i>?</i>	P95B-805-295-E -	1		-	\$ 301.70
14	GUIDE PIECE LH <i>?</i>	P95B-807-889-C -	1		-	\$ 103.80
15	STRUT BRACE LH <i>?</i>	P95B-805-527- -	1		-	\$ 132.20
16	BONNET <i>SCA /</i>	P95B-823-031-LY-GRV	1		-	\$ 5,534.70
17	GASKET FOR ENGINE COVER <i>SCA /</i>	P95B-823-739- -	2		-	\$ 21.80
18	PORSCHE CREST <i>SCA /</i>	P9P1-853-601- -	1		-	\$ 356.50
19	DESK PAD CREST <i>SCA /</i>	P9P1-853-611- -	1		-	\$ 21.30
20	HOOD BADGE NUT <i>SCA /</i>	PWHT-004-974- -	2		-	\$ 4.60
21	HEADLAMP (LEFT) <i>X</i>	P95B-941-029-FA-	1		-	\$ 4,185.90
22	ADDITIONAL HEADLAMP LH <i>SCA /</i>	P95B-941-181-E -	1		-	\$ 466.90
23						\$ -

Sub-Total (Parts Price) \$ - \$ **13,909.50**
**LABOUR / SERVICES CHARGES**

NO	DESCRIPTION	REVISED	PRICE
1	TO REMOVE /REPLACE BONNET, FRONT BUMPER & ALL ACCIDENT DAMAGED BODY PARTS. TO REPAIR ALL AREAS AFFECTED BY THE ACCIDENT.	<i>3440</i>	\$ 5,160.00
2	TO RESPRAY BONNET, FRONT BUMPER	<i>2600</i>	\$ 3,000.00
3	TO CARRY-OUT BODY CAVITY PRESERVATION.	<i>150</i>	\$ <del>250.00</del>



**REPAIR ESTIMATE**

4	TO SUPPLY 1 PC CHASSIS STICKER ON BONNET	nett	\$ 150.00
5	TO REMOVE & REPLACE CHARGE AIR COOLER BRACKET LH	nett	\$ ? 780.00
6	TO TOP-UP GAS, CONDUCT PRESSURE TEST & PERFORM LEAK TEST ON THE COOLING SYSTEM.	nett	\$ ? 500.00
7	TO TRANSFER THE FRONT BUMPER SENSORS.	nett	\$ 250 500.00
8	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.		\$ 150 250.00
9	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.	nett	\$ 600.00
10	SUNDRIES.	nett	\$ 20 50.00

Survey Date & Time: <b>21/08/24</b>	Repair Days: <b>4 days</b>	Excess:
--	-------------------------------	---------

Surveyor Remarks:

*Rasul  
Hp 90010068  
Res by paint*

**Remarks:**

- This is only an estimate based on visual inspection. Should there be more damages found during repair, it will be informed and quoted additionally.
- An administrative fee of 20% of the quotation value will be chargeable for damage assessment and preparation of this estimate, if you choose not to proceed with repair.

Sub-Total (Labour Price) \$ - \$ 11,240.00

	REVISED	PRICE
Parts Price	\$ -	\$ 13,909.50
Labour Price	\$ -	\$ 11,240.00
Total (Initial Estimate)	\$ -	\$ 25,149.50
Supp 1	\$ -	\$ -
Supp 2	\$ -	\$ -
Supp 3	\$ -	\$ -
Total (Before Excess)	\$ -	\$ 25,149.50
Less Excess	\$ -	\$ -
TOTAL (After Excess)	\$ -	\$ 25,149.50
GST 9%	\$ -	\$ 2,263.46
<b>GRAND TOTAL</b>	\$ -	\$ 27,412.96

LKK Auto Consultants hence not the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Singapore NRIC
Owner ID:	809J
<b>Vehicle Details</b>	
Vehicle No.:	SKU34L
Vehicle to be Exported:	No
Intended Deregistration Date:	22 Aug 2024
Vehicle Make:	PORSCHE
Vehicle Model:	MACAN PDK CYP E6
Primary Colour:	Grey
Manufacturing Year:	2017
Engine No.:	097376
Chassis No.:	WP1ZZZ95ZJLB06094
Maximum Power Output:	185.0 kW (248 bhp)
Open Market Value:	\$63,703.00
Original Registration Date:	23 Feb 2018
First Registration Date:	23 Feb 2018
Transfer Count:	1
Actual ARF Paid:	\$86,666.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Feb 2028
PARF Rebate Amount:	\$56,332.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	22 Feb 2028
COE Category:	E - Open - all except motorcycle
COE Period(Years):	10
QP Paid:	\$39,903.00
COE Rebate Amount:	\$13,966.00
<b>Total Rebate Amount:</b>	<b>\$70,298.00</b>
<b>Message</b>	
You will not be eligible for any COE rebate from the current COE (including unused COE from any lay-up period/s), if you renew your COE.	

The information contained herein is correct as at 22 Aug 2024

OK



## Porsche Macan 2.0A PDK

**\$163,800** Instalment \$2,660/mth

PREMIUM AD

💰 Apply for 2.48% loan

♡ Shortlist

✓ Get Warranty



### Overview Financial Photo Research

Depreciation	📘 \$35,030 / year
Reg. Date	09-Feb-2018 (3yrs 5mths 17days COE left)
Manufactured	📘 2017
Mileage	149,000 km (22.8k / year)
Transmission	Auto
Engine Cap	1,984 cc
Road Tax	📘 \$1,194 / year
Power	185.0 kW (248 bhp) <a href="#">View specs of the Porsche Macan (2014-2019)</a>
Curb Weight	📘 1,845 kg
COE	📘 \$48,011
OMV	📘 \$62,656
ARF	📘 \$84,781