



MOTORSPORTS

JD MOTORSPORTS PTE LTD
25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 16/08/24
VEHICLE : SMQ1086C
MAKE/MODEL : TOYOTA AXIO
CHASSIS NO : NKE165-7221026
MILLAGE : 311217KM
TYRE SIZE : 185/60 R15
DOA : 13/08/24

Not Withheld
61 Rmp & 1900p
Presurvey After Paint
4 days

List items

01 PC REAR LH DOOR
01 PC REAR LH DOOR INNER LOCK
01 PC REAR LH DOOR CATCH LOCK
01 PC REAR LH DOOR WEATERSTRIP
01 PC REAR LH POWER WINDOW REGULATOR
01 PC REAR LH POWER WINDOW MOTOR
01 PC REAR LH FENDER
01 PC REAR LH RIM COVER 170
01 PC REAR LH WHEEL BEARING with hub
01 PC REAR LH ABSORBER
01 PC REAR AXLE

Rollwrap \$ 1,294.02 ✓
R \$ 466.29 X
R \$ 38.31 X
L \$ 219.28 X
\$ L 189.75 X
\$ L 755.43 X
\$ R 1,275.93 X
rollwrap \$ 234.96 ✓
\$ R 386.50 ✓
\$ L 322.92 X
R \$ 1,904.88 X
\$ 7,088.27

TOTAL PARTS COST

250

Special Nett Item:

01 PC REAR LH RIM
01 PC REAR LH TYRES
01 PC WINDSCREEN SEALANT

\$ R 250.00 X
\$ L 200.00 X
\$ W 50.00 X
\$ 500.00

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA
3. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS
5. TO SUPPLY LABOUR TO REMOVE AND REFIX REAR UNDER CARRIGE
6. TO SUPPLY LABOUR TO DISMANTLE AND REFIX REAR WINDSCREEN
7. TO SUPPLY LABOUR TO DISMANTLE REAR INNER FENDER UPHOLSTERY
8. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGNMENT
9. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING

\$ 1,500.00 400l
\$ 600.00 400l
\$ 100.00 30l
\$ 100.00 20l
\$ 300.00 80l
R \$ 200.00 X
\$ 200.00 60l
\$ 150.00 60l
\$ W 50.00 X
\$ 3,200.00

TOTAL PARTS
SPECIAL NETT ITEM
TOTAL LABOUR
TOTAL COST OF REPAIR

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

\$ 7,088.27
\$ 500.00
\$ 3,200.00
\$ 10,788.27



Measurement printout

Car standard measurement

Beissbarth © * SL

M * R+ ** OK * AP / 11.00 / 907213 / C

Date: 15.08.2024 12:53:39

Version (program)
v5.0b3224/v5.0b3224Version (FWA)
v5.0b1801Version (target data)
Asia Pacific cars v11.00Serial number
QZ0000178Last service
12.05.2023

Customer

SU BROTHER

Company:

Order

Vehicle

SMQ 1086 C

VIN:

Vehicle:

Asia Pacific cars v11.00

TOYOTA * Carolla Axio * NRE160 * 2WD

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-12°47'	-0°30' [-0°55'] +0°30'	-13°02'
	right	-0°47'		-0°51'
Cross Camber		-12°00'	[0°30']	-12°12'
Individual Toe	left	-0°41'	-0°15' [+0°15'] +0°15'	-0°37'
	right	+0°35'		+0°37'
Total Toe		-0°06'	-0°29' [+0°29'] +0°29'	-0°01'
Setback		-0°09'		-0°08'
Geometrical driving axis		+0°37'		
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+3°26'	-0°45' [+4°55'] +0°45'	+3°27'
	right	+4°01'		+4°02'
K.P.I. 20°	left	+28°15'	[11°20']	
	right	+19°55'	[11°20']	
Toe out on turns	left	-1°05'		
	right	-1°08'		
Camber	left	-0°44'	-0°45' [-0°10'] +0°45'	-0°44'
	right	-0°49'		-0°50'
Cross Camber		+0°05'	[0°30']	+0°06'
Individual Toe	left	+0°11'	-0°10' [+0°05'] +0°10'	-0°01'
	right	-0°01'		+0°11'
Total Toe		+0°10'	-0°19' [+0°10'] +0°19'	+0°10'
Setback		-0°14'		-0°04'
Included Angle 20°	left	+27°18'		
	right	+19°17'		