



Finalise QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 1
DOCUMENT NO.: 2765
DOCUMENT DATE: 01/10/2024
POS ID: 12
PRINTED BY: Joseph Tee
SERVICE ADV:
CSP/OP CODE: Joseph Tee
DEPT: I
WIP NO.: 15048
REF. NO.: DS/SMV6959A/2048
DATE IN: 27/08/2024
EXT. WTY: 14/10/2025
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: MAZDA6 IPM4 2L SDN STD BLACK L
CHASSIS NO.: JM6GL1073L0404817
ENGINE NO.: PE21346573
REG NO.: SMV6959A
REGN DATE: 15/10/2020

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
NOTES	SMV6959A -DOA:14/8/2024 -DS -China Taiping				0.00	O
SUB	TO REMOVE & REPLACE REAR BUMPER & BOOTLID.				1,592.00	S
	TO REPAIR END PANEL.					
	AND ALL ACCIDENT AFFECTED AREA.					
SUB	TO RESPRAY REAR BUMPER, BOOTLID & REAR				1,504.00	S
	REINFORCEMENT.					
SUB	TO TRANSFER REVERSE SENSORS.				330.00	S
SUB	TO CARRY OUT BODY CAVITY PRESERVATION.					
SUB	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIO				180.00	S
SUB	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WO				250.00	S
SUB	SUNDRIES.				20.00	S
GSK1-50-221AB	REAR BUMPER W/PK SENSOR GL	1.00	1,260.75	*ISSUED	1,260.75	S
BHN1-50-0Z1A	GROMMET,SCREW	4.00	2.36	*ISSUED	9.44	S
GSH7-50-2G1	RUBBER, SEAL GL	2.00	13.91	*ISSUED	27.82	S
C274-50-133	NUT,CLIP	4.00	2.36	*ISSUED	9.44	S
TK21-50-355	RIVET	2.00	7.42	*ISSUED	14.84	S
EA01-50-037	RIVET	6.00	7.34	*ISSUED	44.04	S
GSH7-50-EL1	BBCOVER(L),TOWING HOOK GL3	1.00	56.22	*ISSUED	56.22	S
GSH7-50-EK1	BBCOVER(R),TOWING HOOK GL3	1.00	56.22	*ISSUED	56.22	S
B45A-56-146A	FASTENER	6.00	2.36		14.16	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :

5 Ubi Close Singapore 408605

Sales Tel: 6395 8888 Service Tel: 6395 8899

Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095

Sales Tel: 6603 6118 Service Tel: 6603 6128

Sales Fax: 6476 7073 Service Fax: 6476 7417



Finalise -QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 2
DOCUMENT NO.: 2765
DOCUMENT DATE: 01/10/2024
POS ID: 12
PRINTED BY: Joseph Tee
SERVICE ADV:
CSP/OP CODE: Joseph Tee
DEPT: I
WIP NO.: 15048
REF. NO.: DS/SMV6959A/2048
DATE IN: 27/08/2024
EXT. WTY: 14/10/2025
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: MAZDA6 IPM4 2L SDN STD BLACK L
CHASSIS NO.: JM6GL1073L0404817
ENGINE NO.: PE21346573
REG NO.: SMV6959A
REGN DATE: 15/10/2020

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
11-BCKA-50-0Z	GROMMET,SCREW	4.00	2.36	*ISSUED	9.44	S
KD47-67-UC5A1	RETAINER S/ACTIV	2.00	15.77	*ISSUED	31.54	S
KD45-67-UC5A1	RETAINER RR SENSOR GL	2.00	15.77	*ISSUED	31.54	S
KD47-67-UC1	1.SENSOR,ULTRASONIC GJ/KG	2.00	184.59	*ISSUED	369.18	S
BCKA-50-EM1	TAPE,PROTECTOR	4.00	7.42	*ISSUED	29.68	S
GDDL-67-290	CORD SHORT RR. BUMPER GL	1.00	215.94	*ISSUED	215.94	S
GRF5-51-153	GASKET(R),RR.COMB. GL3	1.00	52.77	*ISSUED	52.77	S
GRF5-51-163	GASKET(L),RR.COMB. GL3	1.00	52.77	*ISSUED	52.77	S
GHP9-51-146	FASTENER	2.00	2.36	*ISSUED	4.72	S
KD53-51-146B	FASTENER	2.00	3.71	*ISSUED	7.42	S
GRF5-51-3H8	GASKET(R), LAMP-TRUNK LID GL3	1.00	82.18	*ISSUED	82.18	S
GRF5-51-3J8	GASKET(L), LAMP-TRUNK LID GL3	1.00	82.18	*ISSUED	82.18	S
EG21-51-146	FASTENER	2.00	5.57	*ISSUED	11.14	S
GBY2-52-61X	TRUNK LID GL3	1.00	1,093.78	*ISSUED	1,093.78	S
D24H-62-866	COVER,HOLE RR LID S/ACTIV	3.00	2.36	*ISSUED	7.08	S
GDDC-51-721A	ORNAMENT RR "MAZDA 6" GL	1.00	62.29	*ISSUED	62.29	S
GBEF-51-730A	MASCOT,REAR GL3	1.00	50.15	*ISSUED	50.15	S
GDDL-51-771	ORNAMENT "SKYACTIV G" GL	1.00	52.60	*ISSUED	52.60	S
GHK1-50-260	REINF REAR BUMPER GJ/GL	1.00	523.08	*ISSUED	523.08	S
GMK6-67-UC1	1SENSOR,ULTRASONIC KE/BN/KG	1.00	184.59	*ISSUED	184.59	S

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.



Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN.199103859N, GST Regn. No.: M90364005A

Showrooms & Service Centres :

5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402

23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417



Finalise QUOTATION

CODE: C0006
CUSTOMER: CHINA TAIPING (SINGAPORE) PTE LT
ADDRESS: 3 ANSON ROAD
#16-00 SPRINGLEAF TOWER
SINGAPORE 079909

PAGE NO.: 3
DOCUMENT NO.: 2765
DOCUMENT DATE: 01/10/2024
POS ID: 12
PRINTED BY: Joseph Tee
SERVICE ADV:
CSP/OP CODE: Joseph Tee
DEPT: I
WIP NO.: 15048
REF. NO.: DS/SMV6959A/2048
DATE IN: 27/08/2024
EXT. WTY: 14/10/2025
MILEAGE: 0

CONTACT NO.: 6389 6111
MODEL: MAZDA6 IPM4 2L SDN STD BLACK L
CHASSIS NO.: JM6GL1073L0404817
ENGINE NO.: PE21346573
REG NO.: SMV6959A
REGN DATE: 15/10/2020

DESCRIPTION: Body repair

Item	Description	Qty.	Unit Price	Stk/Status	Gross amount	GST Code
			SGD		SGD	
GBEF-50-85ZA	MOULD,TRUNK LID GL3	1.00	412.92	*ISSUED	412.92	S

	* GST Code	Rate	Service/Goods	GST	Before GST	GST	Total
Parts	O	-		-	8,885.92	799.73	9,685.65
Surcharge	S	9.00%	8,885.92	799.73	0.00	0.00	0.00
Labour							
Menus							
					Amount Due	8,885.92	9,685.65

*This is only an estimate from our visual inspection and should there be more damages found during the process of works you will then be informed for your approval before proceeding with the repairs.

*Take note that should you decide not to proceed with the repairs "a service quotation fee" with a minimum of \$180.00 will be applied and it will varies depending on the time unit that was taken for the checking and diagnosis of your vehicle.

**Deposit tax invoice No.:

CASH / NETS / AMEX / VISA / MASTER / CHEQUE
No.

Date: _____ Customer signature _____ Authorised signature _____
TRANS EUROKARS Corporate Head Office : Trans Eurokars Pte Ltd, 11 Kung Chong Road Singapore 159147
Tel: 6363 3003, Fax: 63693003, BRN: 199103859N, GST Regn. No.: M90364005A

zoom-zoom

Showrooms & Service Centres :
5 Ubi Close Singapore 408605
Sales Tel: 6395 8888 Service Tel: 6395 8899
Sales Fax: 68461700 Service Fax: 6744 9402
23 Leng Kee Road Singapore 159095
Sales Tel: 6603 6118 Service Tel: 6603 6128
Sales Fax: 6476 7073 Service Fax: 6476 7417