



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 17/08/24
VEHICLE : SKV1480U
MAKE/MODEL : TOYOTA ALTIS
CHASSIS NO : MR053REH104538005
MILLAGE : 145369KM
TYRE SIZE : 205/55 R16
DOA : 15/08/24

Not Authorized
11/18/24 86100t Max
Recovery After Paving
6 days

List items

01 PC	FRONT BUMPER	639.80	Avl/cm	\$ 1,599.95	✓
01 PC	FRONT BUMPER LOWER GANISH		\$m	\$ 332.48	X
01 PC	FRONT BUMPER FOG LAMP RH		\$m	\$ 365.80	X
01 PC	FRONT BUMPER FOG LAMP COVER RH		\$m	\$ 182.96	X
01 PC	FRONT BUMPER FOG LAMP BRACKET		\$m	\$ 68.15	X
01 PC	FRONT BUMPER SIDE RETAINER RH	90.40	CRP	\$ 182.60	✓
01 PC	FRONT BUMPER UNDER COVER		\$m	\$ 312.68	X
01 PC	FRONT GRILLE ASSY	680.70	CRP	\$ 1,281.00	✓
01 PC	FRONT GRILLE EMBLEM 'LOGO'	74.20	\$m	\$ 135.20	✓
01 PC	FRONT SUPPORT PANEL TOP GANISH		\$m	\$ 118.20	X
01 PC	FRONT BUMPER REINFORCEMENT		\$m	\$ 658.30	X
01 PC	FRONT BUMPER FOAM		\$m	\$ 213.57	X
01 PC	FRONT HEAD LAMP RH		GR	\$ 2,227.50	✓
01 PC	FRONT HEAD LAMP LOWER BRACKET RH		\$m	\$ 186.70	X
01 PC	FRONT HEAD LAMP TOP CHROME GANISH RH		\$m	\$ 205.30	X
01 PC	FRONT HEAD LAMP TOP PANEL RH		\$m	\$ 257.80	X
01 PC	FRONT BONNET		\$m	\$ 1,545.40	X
01 PC	FRONT BONNET HINGES RH		\$m	\$ 116.40	X
01 PC	FRONT WIPER PANEL SIDE GANISH RH		\$m	\$ 125.60	X
01 PC	FRONT FENDER RH	761.45	\$m	\$ 993.20	✓
01 PC	FRONT FENDER INNER GANISH	210	\$m	\$ 249.00	✓
01 PC	FRONT FENDER EMBLEM 'VVTI'	55	\$m	\$ 85.95	✓
01 PC	FRONT FENDER INNER PANEL RH		\$m	\$ 183.30	X
01 PC	FRONT FENDER INNER SHEILD RH		\$m	\$ 328.60	X
01 PC	FRONT ENGINE SIDE COVER RH		\$m	\$ 147.16	X
01 PC	WIPER TANK		\$m	\$ 325.90	X
01 PC	FRONT SIDE MIRROR ASSY RH	1180.50	\$m	\$ 1,417.50	✓
01 PC	FRONT SIDE MIRROR COVER RH		\$m	\$ 139.76	✓
01 PC	FRONT DOOR RH	1665.20	\$m	\$ 2,136.96	✓
01 PC	FRONT DOOR CHECKER RH	152	\$m	\$ 263.50	✓
02 PC	FRONT DOOR HINGES RH @	\$110.65	\$m	\$ 221.30	X
01 PC	FRONT DOOR OUTER MOULDING RH		\$m	\$ 318.80	X
01 PC	FRONT DOOR INNER SEAL RUBBER RH		\$m	\$ 201.30	X
01 PC	FRONT DOOR TRIM BOARD RH		\$m	\$ 753.90	X
01 PC	FRONT DOOR POWER WINDOW MOTOR RH		\$m	\$ 871.64	X

01 PC	FRONT DOOR POWER WINDOW REGULATOR RH	Sm	\$	566.20	X
01 PC	FRONT DOOR GLASS RAILWAY RH	Sm	\$	243.60	X
01 PC	FRONT DOOR GLASS RUBBER RH	Sm	\$	201.69	X
01 PC	FRONT DOOR SPEAKER RH	Sm	\$	529.20	X
01 PC	FRONT DOOR WEATERSTRIP RH	Sm	\$	299.07	X
01 PC	FRONT KNAKLER RH 585	Bz	\$	942.50	2
01 PC	FRONT WHEEL BEARING RH 128-10	mm	\$	364.90	2
01 PC	FRONT LOWER ARM RH	mm	\$	567.10	2
01 PC	FRONT LOWER ARM BALL JOINT RH	Sm	\$	284.60	X
01 PC	FRONT ABSORBER RH 438	Bz	\$	561.70	2
01 PC	FRONT ABSORBER MOUNTING RH	Sm	\$	254.30	X
01 PC	FRONT STERRING RACK	Sm	\$	2,462.20	X
01 PC	FRONT WHEEL SPEED SENSOR RH	Sm	\$	381.30	X
TOTAL PARTS COST				258	\$ 26,411.72

Special Nett Item:

01 PC	FRONT RIM RH	mm	\$	600.00	280mm
01 PC	FRONT TYRES RH	Sm	\$	250.00	X
06 PC	FRONT GRILLE CLIP @ \$8.00	mm	\$	48.00	—
10 PC	FRONT BUMPER CLIP @ \$8.00	mm	\$	80.00	—
10 PC	FRONT INNER SHEILD CLIP @ \$8.00	mm	\$	80.00	—
10 PC	FRONT DOOR TRIM BOARD CLIP @ \$8.00	Sm	\$	80.00	—
08 PC	FRONT BUMPER UNDER COVER CLIP @ \$8.00	Sm	\$	64.00	—
06 PC	FRONT ENGINE SIDE COVER CLIP @ \$8.00	Sm	\$	48.00	—
01 PC	FRONT NUMBER PLATE	\$ Bz		30.00	} 45mm
01 PC	FRONT NUMBER PLATE COVER	\$		20.00	
				\$ 1,300.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,500.00	600l
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$	1,000.00	680l
3. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	250.00	60l
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	20l
5. TO SUPPLY LABOUR TO DISMANTLE & REFIX UNDER CARRIGE	\$	250.00	200l
6. TO SUPPLY LABOUR TO DISMANTLE & REFIX DOOR INNDER UPHOLSTER	\$	100.00	60l
7. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGNMENT	\$	120.00	60l
8. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING	\$	50.00	20l
9. TO SUPPLY LABOUR TO DIANOGTIC & REPROGRAMMING	Sm	250.00	X
		\$ 3,720.00	

TOTAL PARTS	\$	26,411.72
SPECIAL NETT ITEM	\$	1,300.00
TOTAL LABOUR	\$	3,720.00
TOTAL COST OF REPAIR	\$	31,431.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Measurement printout

Car standard measurement

Beissbarth © * SL

M * R+ ** OK * AP / 11.00 / 926119 / C

Date: 15.08.2024 12:25:24



Version (program) v5.0b3224/v5.0b3224	Version (FWA) v5.0b1801	Version (target data) Asia Pacific cars v11.00	Serial number QZ0000178	Last service 12.05.2023
--	----------------------------	---	----------------------------	----------------------------

Customer

Company: SU BROTHER

Vehicle

VIN: SKV 1480 U

Order

Vehicle: Asia Pacific cars v11.00
TOYOTA * Altis

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-1°51'		-1°46'
	right	-1°36'		-1°39'
Individual Toe	left	+0°02'		-0°04'
	right	+0°24'		+0°28'
Total Toe		+0°26'		+0°24'
Setback		+0°08'		+0°07'
Geometrical driving axis		+0°10'		
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+2°41'		+2°41'
	right	+6°38'	-1°00' [+2°45'] +1°00'	+6°38'
K.P.I. 20°	left	+17°35'		
	right	+12°05'		
Toe out on turns	left	-2°06'		
	right	-0°38'		
Camber	left	-1°26'		-1°24'
	right	-10°36'	-0°30' [-0°30'] +0°30'	-10°58'
Individual Toe	left	+0°06'		+0°07'
	right	-0°45'	-0°02' [+0°05'] +0°03'	-0°48'
Total Toe		-0°39'	-0°05' [+0°10'] +0°05'	-0°42'
Setback		+0°20'		+0°17'
Included Angle 20°	left	+16°04'		
	right	+4°42'		