

ASS. REC. BY:

REF:

LPC / CS/LPC24080268/Kvh3e2

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / QD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured: XD 8666X

Policy No.

Claims No. 24/24/24/VC05/029713

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

06

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

22/8

212m

86100m

Cah

(red 25,331.72, 80%)

Veh No:

SKV 1480X

Yr Regn:

08, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Tuy AIAIS

C.C.

1598

Colour

M. Gray

A/C:

Insured / Std / NI / NA

Sp. Reading

145369

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

MR053REH104538005

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

205/55R16

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Front

Rear

R/Bal.

5

mm

R/Bal.

8

mm

L/Bal.

5

mm

L/Bal.

8

mm

D.O.A.

15/8/24

D.O.I.

19/8/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

O/S Air body & U/C

The U/C / Chassis frame / Body Structure affected due to collision.

Date/Time, File Pass to?

☐

: Prel. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

6

Resurvey No. of Trip:

Survey Fee:

Transportation

S - RS. SI

Fees

Others

TOTAL

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$



MOTORSPORTS

JD MOTORSPORTS PTE LTD

25 KAKI BUKIT RD 4 # 05-76 SYNERGY @ KB S417800

DATE : 17/08/24
VEHICLE : SKV1480U
MAKE/MODEL : TOYOTA ALTIS
CHASSIS NO : MR053REH104538005
MILLAGE : 145369KM
TYRE SIZE : 205/55 R16
DOA : 15/08/24

Not Authorized
11 Pym \$6100t Max
Penny After Paim
6 days

List items

01 PC	FRONT BUMPER	639.80	Pr/cem	\$	1,599.95	✓
01 PC	FRONT BUMPER LOWER GANISH		Pr	\$	332.48	X
01 PC	FRONT BUMPER FOG LAMP RH		Pr	\$	365.80	X
01 PC	FRONT BUMPER FOG LAMP COVER RH		Pr	\$	182.96	X
01 PC	FRONT BUMPER FOG LAMP BRACKET		Pr	\$	68.15	X
01 PC	FRONT BUMPER SIDE RETAINER RH	90.40	CRP		182.60	✓
01 PC	FRONT BUMPER UNDER COVER		\$Pr		312.68	X
01 PC	FRONT GRILLE ASSY	680.70	CRP	\$	1,281.00	✓
01 PC	FRONT GRILLE EMBLEM 'LOGO'	74.20	Pr	\$	135.20	✓
01 PC	FRONT SUPPORT PANEL TOP GANISH		Pr	\$	118.20	X
01 PC	FRONT BUMPER REINFORCEMENT		\$Pr		658.30	X
01 PC	FRONT BUMPER FOAM		\$Pr		213.57	X
01 PC	FRONT HEAD LAMP RH		Gr	\$	2,227.50	✓
01 PC	FRONT HEAD LAMP LOWER BRACKET RH		\$Pr		186.70	X
01 PC	FRONT HEAD LAMP TOP CHROME GANISH RH		Pr	\$	205.30	X
01 PC	FRONT HEAD LAMP TOP PANEL RH		\$Pr		257.80	X
01 PC	FRONT BONNET		\$Pr		1,545.40	X
01 PC	FRONT BONNET HINGES RH		\$Pr		116.40	X
01 PC	FRONT WIPER PANEL SIDE GANISH RH		\$Pr		125.60	X
01 PC	FRONT FENDER RH	761.45	Pr	\$	993.20	✓
01 PC	FRONT FENDER INNER GANISH	210	Pr	\$	249.00	✓
01 PC	FRONT FENDER EMBLEM 'VVTI'	55	\$Pr		85.95	✓
01 PC	FRONT FENDER INNER PANEL RH		\$Pr		183.30	X
01 PC	FRONT FENDER INNER SHEILD RH		\$Pr		328.60	X
01 PC	FRONT ENGINE SIDE COVER RH		\$Pr		147.16	X
01 PC	WIPER TANK		\$Pr		325.90	X
01 PC	FRONT SIDE MIRROR ASSY RH	1180.50	Pr	\$	1,417.50	✓
01 PC	FRONT SIDE MIRROR COVER RH		Pr	\$	139.76	✓
01 PC	FRONT DOOR RH	1665.20	Pr	\$	2,136.96	✓
01 PC	FRONT DOOR CHECKER RH	152	\$Pr		263.50	✓
02 PC	FRONT DOOR HINGES RH @ \$110.65		\$Pr		221.30	X
01 PC	FRONT DOOR OUTER MOULDING RH		\$Pr		318.80	X
01 PC	FRONT DOOR INNER SEAL RUBBER RH		\$Pr		201.30	X
01 PC	FRONT DOOR TRIM BOARD RH		\$Pr		753.90	X
01 PC	FRONT DOOR POWER WINDOW MOTOR RH		\$Pr		871.64	X

01 PC	FRONT DOOR POWER WINDOW REGULATOR RH	Sm	\$	566.20	X
01 PC	FRONT DOOR GLASS RAILWAY RH	Sm	\$	243.60	X
01 PC	FRONT DOOR GLASS RUBBER RH	Sm	\$	201.69	X
01 PC	FRONT DOOR SPEAKER RH	Sm	\$	529.20	X
01 PC	FRONT DOOR WEATERSTRIP RH	Sm	\$	299.07	X
01 PC	FRONT KNAKLER RH ⁵⁸⁵	Bz	\$	942.50	✓
01 PC	FRONT WHEEL BEARING RH ^{128.10}	Ma	\$	364.90	✓
01 PC	FRONT LOWER ARM RH	D/S	\$	567.10	✓
01 PC	FRONT LOWER ARM BALL JOINT RH	Sm	\$	284.60	X
01 PC	FRONT ABSORBER RH ⁴³⁸	Bz	\$	561.70	✓
01 PC	FRONT ABSORBER MOUNTING RH	Sm	\$	254.30	X
01 PC	FRONT STERRING RACK	Sm	\$	2,462.20	X
01 PC	FRONT WHEEL SPEED SENSOR RH	Sm	\$	381.30	X
TOTAL PARTS COST				\$ 26,411.72	

258

Special Nett Item:

01 PC	FRONT RIM RH	Ma	\$	600.00	2800
01 PC	FRONT TYRES RH	Sm	\$	250.00	X
06 PC	FRONT GRILLE CLIP @ \$8.00	Ma	\$	48.00	—
10 PC	FRONT BUMPER CLIP @ \$8.00	Ma	\$	80.00	—
10 PC	FRONT INNER SHEILD CLIP @ \$8.00	Ma	\$	80.00	—
10 PC	FRONT DOOR TRIM BOARD CLIP @ \$8.00	Sm	\$	80.00	✓
08 PC	FRONT BUMPER UNDER COVER CLIP @ \$8.00	Sm	\$	64.00	✓
06 PC	FRONT ENGINE SIDE COVER CLIP @ \$8.00	Sm	\$	48.00	✓
01 PC	FRONT NUMBER PLATE	Bz	\$	30.00	} 450
01 PC	FRONT NUMBER PLATE COVER	\$	\$	20.00	
				\$ 1,300.00	

Labour:

1. TO SUPPLY PARTS & LABOUR TO REPLACE ABOVE MENTIONED PARTS	\$	1,500.00	600
2. TO SUPPLY PAINT & LABOUR TO SPRAY ACCIDENT AFFECT AREA	\$	1,000.00	680
3. TO SUPPLY LABOUR TO SPRAY ANTI RUST ON PANEL	\$	250.00	60
4. TO SUPPLY LABOUR TO REWIRE REPLACE PARTS	\$	200.00	20
5. TO SUPPLY LABOUR TO DISMANTLE & REFIX UNDER CARRIGE	\$	250.00	200
6. TO SUPPLY LABOUR TO DISMANTLE & REFIX DOOR INNDER UPHOLSTER	\$	100.00	60
7. TO SUPPLY LABOUR TO CONDUCT WHEEL ALIGNMENT	\$	120.00	60
8. TO SUPPLY LABOUR TO CONDUCT WHEEL BALANCING	\$	50.00	20
9. TO SUPPLY LABOUR TO DIANOGTIC & REPROGRAMMING	Sm	250.00	X
		\$ 3,720.00	

TOTAL PARTS

\$ 26,411.72

SPECIAL NETT ITEM

\$ 1,300.00

TOTAL LABOUR

\$ 3,720.00

TOTAL COST OF REPAIR

\$ 31,431.72

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Measurement printout

Car standard measurement

Beissbarth © * SL

M * R+ ** OK * AP / 11.00 / 926119 / C

Date: 15.08.2024 12:25:24



Version (program) v5.0b3224/v5.0b3224	Version (FWA) v5.0b1801	Version (target data) Asia Pacific cars v11.00	Serial number QZ0000178	Last service 12.05.2023
--	----------------------------	---	----------------------------	----------------------------

Customer

Company: SU BROTHER

Vehicle

VIN: SKV 1480 U

Order

Vehicle: Asia Pacific cars v11.00
TOYOTA * Altis

Rear Axle		Initial Measurement	Target Data	Final Measurement
Camber	left	-1°51'		-1°46'
	right	-1°36'		-1°39'
Individual Toe	left	+0°02'		-0°04'
	right	+0°24'		+0°28'
Total Toe		+0°26'		+0°24'
Setback		+0°08'		+0°07'
Geometrical driving axis		+0°10'		
Front Axle		Initial Measurement	Target Data	Final Measurement
Castor 20°	left	+2°41'		+2°41'
	right	+6°38'	-1°00' [+2°45'] +1°00'	+6°38'
K.P.I. 20°	left	+17°35'		
	right	+12°05'		
Toe out on turns	left	-2°06'		
	right	-0°38'		
Camber	left	-1°26'		-1°24'
	right	-10°36'	-0°30' [-0°30'] +0°30'	-10°58'
Individual Toe	left	+0°06'		+0°07'
	right	-0°45'	-0°02' [+0°05'] +0°03'	-0°48'
Total Toe		-0°39'	-0°05' [+0°10'] +0°05'	-0°42'
Setback		+0°20'		+0°17'
Included Angle 20°	left	+16°04'		
	right	+4°42'		