

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN		Ref:	CS/INC24080269/Anh3e2(N)		
	75 BRAS BASAH R		Date:	24/10/2025		
	ATTN: JULIE			Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNB 9290T	Veh. Inspected	k	FBN 8822U	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1290702-002	Excess (\$)		0.00	
	Assign From	ANNA YEO	Assign Date		18/08/2024	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA SUPRA GTR	c.c		149	
	Engine No.	HIDDEN	Year of Reg.		2018	
	Chassis No.	MH1KB2113JK079105	Colour		BLACK	
	Odometer	-	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	90/80 R17	PIRELLI		6 mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre	120/70 R17	MAXXIS		6 mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S AND N/S BODY.					
	DAMAGES SEE DETAILS.					
5. General Information						
	Accident Date	14/08/2024	Inspect Date /	Time	16/08/2024 (01:45 PM)	
	Survey held at	MS CAR AUTO PTE LTD				
		8 KAKI BUKIT AVENUE 4 #01-07 PREMIER @ KAKI BUKIT SINGAPORE 415875				
5a.	5a. Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days					