

MG SOLUTION PTE LTD

23 Kaki Bukit Avenue 4 #04-01 Vicom Inspection Centre Singapore 415933

Tel: 6744 4986

Reg. No: 201427944N

Email: MG3SOLUTION@GMAIL.COM

ATTENTION:	MOTOR CLAIMS DEPARTMENT	Xiao Chen.
DATE:	15-08-24	
CLAIM TYPE:	T/P CLAIM	
TO:	INCOME	
VEHICLE DETAILS		
VEHICLE NO:	SMP4616J	
MAKE & MODEL:	TOYOTA NOAH	
CHASSIS NO:		
ACCIDENT DETAILS		
DATE:	6 August, 2024	
TIME:	1714HRS	
THIRD PARTY REQUESTOR:	JACK LI	

CLAIM DETAILS: PARTS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	TAIL GATE <i>Dented</i>	1	\$ 2,050.50	\$ 2,050.50
2	TAILGATE HRBIRD EMBLEM <i>new</i>	1	\$ 80.00	\$ 80.00
3	TAIL GATE LOCK <i>new</i>	1	\$ 480.00	\$ 480.00
4	TAIL GATE WEATHERSTRIP <i>new</i>	1	\$ 350.00	\$ 350.00
5	TAIL GATE INNER TRIM BOARD <i>new dented</i>	1	\$ 780.00	\$ 780.00
6	TAIL GATE WINDSCREEN MOULDING <i>new</i>	1	\$ 195.00	\$ 195.00
7	REAR BUMPER <i>Dented</i>	1	\$ 850.00	\$ 850.00
8	REAR BUMPER SIDE RETAINER <i>new dented</i>	1	\$ 62.40	\$ 62.40
9	REAR BUMPER REFLECTOR <i>smashed</i>	1	\$ 90.00	\$ 90.00
10	REAR QUARTER BUMPER <i>Dented</i>	1	\$ 350.00	\$ 350.00
11	REAR QUARTER BUMPER SIDE RETAINER <i>crushed</i>	1	\$ 120.00	\$ 120.00
12	TAILLAMP <i>new</i>	1	\$ 850.00	\$ 850.00
13	REAR FENDER <i>Repair</i>	1	\$ 1,855.30	\$ 1,855.30
14	REAR FENDER INNER TRIM RH <i>new</i>	1	\$ 820.00	\$ 820.00
15	REAR FENDER OUTER GARNISH <i>Repair</i>	1	\$ 780.00	\$ 780.00
16	REAR FENDER MUD FLAG <i>torn</i>	1	\$ 110.00	\$ 110.00
17	REAR END PANEL <i>Dented</i>	1	\$ 680.00	\$ 680.00
18	REAR END PANEL TOP GARNISH <i>new</i>	1	\$ 290.00	\$ 290.00
19	EXHAUST PIPE <i>Best</i>	1	\$ 980.00	\$ 980.00
20	EXHAUST PIPE HEAT SHEILD <i>new</i>	1	\$ 280.00	\$ 280.00
21	EXHAUST PIPE MOUNTING <i>new torn</i>	1	\$ 90.00	\$ 90.00

Missing

HS.

1812

178

685

892

22	AIRCON BLOWER ASSY <i>checked</i>	1	\$ 5,350.00	\$ 5,350.00
----	-----------------------------------	---	-------------	-------------

TOTAL PRICE \$ 17,493.20

LESS 25% \$ 4,373.30

SUB TOTAL PRICE \$ 13,119.90

SPECIAL NETT ITEMS

S/N:	DESCRIPTION	QTY:	UNIT LIST PRICE	TOTAL LIST PRICE
1	REAR NUMBER PLATE <i>new</i>	1	\$ 50.00	\$ 50.00
2	TAILGATE WINDSCREEN SEALANT <i>new</i>	1	\$ 120.00	\$ 120.00
3	TAILGATE INNER TRIM CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
4	REAR BUMPER CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
5	REAR FENDER INNER TRIM CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
6	REAR FENDER MUD FLAG CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
7	REAR END PANEL TOP GARNISH CLIPS SET <i>new</i>	1	\$ 20.00	\$ 20.00
8	REAR END PANEL INSULATION SEALANT <i>new</i>	1	\$ 150.00	\$ 150.00
9	REVERSE SENSOR <i>new</i>	1	\$ 220.00	\$ 220.00

TOTAL \$ 640.00

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)

1	PANEL BEATING, REMOVAL AND REPLACING PARTS	1	\$ 2,000.00	\$ 2,000.00
2	TO SPRAY PAINT AFFECTED AREA	1	\$ 2,000.00	\$ 2,000.00
3	TUFF COAT	1	\$ 250.00	\$ 250.00
4	WIRING CHECK	1	\$ 150.00	\$ 150.00
5	REMOVE AND REFIX CUSHION SEAT/ UPHOLSTERY AND ROOF LINING TO FACILITATE REPAIR	1	\$ 280.00	\$ 280.00
6	REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
7	REMOVE AND REFIX REVERSE CAMERA AND DISTANCE SETTING	1	\$ 100.00	\$ 100.00
8	TRANSFER TAILGATE MECHANISM	1	\$ 120.00	\$ 120.00
9	REMOVE AND REFIX TAILGATE WINDSCREEN	1	\$ 140.00	\$ 140.00
10	REMOVE AND REFIX QUARTER GLASS	1	\$ 120.00	\$ 120.00
11	REMOVE AND REFIX EXHAUST PIPE	1	\$ 250.00	\$ 250.00
12	REMOVE AND REFIX AIRCON BLOWER AND TOP UP GAS	1	\$ 300.00	\$ 300.00

TOTAL \$ 5,810.00

ESTIMATE REPORT

TOTAL PARTS COST \$ 13,759.90

TOTAL LABOUR COST	\$	5,810.00
TOTAL REPAIR COST	\$	19,569.90

APPROVED DETAILS:

SURVEYOR:

CONTACT NO.:

PART BY PART/LUMP SUM

NO. OF DAYS

Adrian L
L/S 19/08/24
00 Days.

total 10388.05
L/S: 8.3K

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8.3K