



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SMQ 6537K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR FENDER RH	TO REPAIR SEE LABOUR	\$1,016.87	\$0.00
1	REAR DOOR RH	TO REPAIR SEE LABOUR	\$2,564.75	\$0.00
	LESS 5.00% DISCOUNT		(\$179.08)	\$0.00
			\$3,402.54	\$0.00
Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CHECK REAR ELECTRICAL WIRING	NOT NECESSARY	\$150.00	\$0.00
	TO TRANSFER DOOR TRIMS	NOT NECESSARY	\$200.00	\$0.00
	TP RESPRAY PAINTING AND ETC		\$800.00	\$300.00
	PANEL BEATING, CUT, WELD REMOVE & REPLACING ABOVE PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH & REAR DOOR RH.		\$800.00	\$400.00
			\$1,950.00	\$700.00
GRAND TOTAL			\$5,352.54	\$700.00
RECOMMENDED COST OF REPAIRS				\$700.00
Report Ref No: CS/AGI24060011/Uqp3e2				

CKS

MARCUS CHUA KANG SENG

Licensed Appraiser