



Automobile Integrated Management Pte Ltd
Co. & G.S.T. Reg no. 201605297G
Workshop: 3021A Ubi Road 1 #01-42 Singapore 408715
Email: automim.claim@gmail.com Tel: 9119 8371

ESTIMATE

Our Ref: C20240038/TP
Vehicle: SMQ6537K BMW Z4 Sdrive
Chassis no.: WBAHF12060WW16199

Date of Loss: 05/06/2024
Insurer: Auto & General
Date of Survey: 14/06/2024

Items	Qty	List Items
1	1	Rear fender RH
2	1	Rear door RH

	Amount \$
<i>R</i>	1,016.87 <i>X</i>
<i>R</i>	2,564.75 <i>X</i>
Sub-total	3,581.62
Less 5%	-179.08
Total Parts	3,402.54

Labour charges

- | | |
|---|---|
| 3 | To check rear electrical wiring |
| 4 | To transfer door trims |
| 5 | To respray painting and etc |
| 6 | Panel beating, cut, weld remove & replacing above parts |

<i>11</i>	150.00 <i>X</i>
<i>11</i>	200.00 <i>X</i>
	800.00 <i>300</i>
	800.00 <i>400</i>
Total Labour	1,950.00

ESTIMATE PARTS AND LABOUR GRAND TOTAL \$

5,352.54

not Audited
in
works
14/6/24
21/2 8700
2 day

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: