

not Authorized  
for  
merch  
18/6/24  
L/S \$5700  
John Phelan

# WE GARAGE

11 Kaki Bukit Avenue 6 #02-11 Autobay @ Kaki Bukit, Singapore 417883

wegarage@consultant.com

Mobile : +65 9009 6622

LKK Auto Consultants hence notify

the Repairer of the following: Date:

• To resurvey before/after spray painting Signature:

• To display damaged part(s) during resurvey Acknowledged by Repairer:

• Parts prices are subject to confirmation

• Under party survey is subject to confirmation

• No illegal modification is allowed

• Supplementary parts must be used

• No illegal modification is allowed

• Under party survey is subject to confirmation

• Parts prices are subject to confirmation

Acknowledged by Repairer: 14 June 2024

Signature: To resurvey before/after spray painting

Date: the Repairer of the following:

LKK Auto Consultants hence notify

REG NO. : SNG 269 P  
MAKE/MODEL : MERCEDES BENZ E200

## ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

| QTY               | DESCRIPTION                              | AMT(\$)               |
|-------------------|------------------------------------------|-----------------------|
| <u>LIST ITEMS</u> |                                          |                       |
| 1                 | Front headlamp -LH <i>cna</i>            | 3677.73 \$ 4,495.00 ✓ |
| 1                 | Front bumper <i>cna/70.1</i>             | 1723.81 \$ 2,198.00 ✓ |
| 1                 | Front bumper clip (1 set) <i>ru</i>      | 60.00 \$ 80.00 ✓      |
| 1                 | Front bumper inner sponge <i>ru</i>      | \$ 165.00 X           |
| 1                 | Front bumper reinforcement <i>R</i>      | \$ 596.00 X           |
| 1                 | Front bumper side retainer <i>ok cna</i> | \$ 75.00 ✓            |
| 1                 | Front bumper side grille <i>1/3 cna</i>  | 86.00 \$ 155.00 ✓     |
| 1                 | Front bumper chrome moulding <i>scn</i>  | 72.00 \$ 125.00 ✓     |
| 2                 | Front bumper side PDC sensors <i>scu</i> | \$ 710.00 X           |
| 1                 | Front fender -LH <i>3.05.77</i>          | 1162.73 \$ 1,550.00 ✓ |
| 1                 | Front fender inner shield <i>twi</i>     | \$ 175.00 ✓           |
| 1                 | Front wheel rim -LH <i>R</i>             | \$ 2,880.00 X         |
| 1                 | Front wheel hub with bearing <i>ru</i>   | \$ 587.54 X           |
| 1                 | Front shock absorber <i>ru</i>           | \$ 727.78 X           |
| 1                 | Front knuckle arm <i>ru</i>              | \$ 1,027.09 X         |
| 1                 | Front lower arm <i>ru</i>                | \$ 1,038.00 X         |
| 1                 | Front top arm <i>ru</i>                  | \$ 479.20 X           |
| 1                 | Front control arm <i>ru</i>              | \$ 437.00 X           |
| 1                 | Stabilizer bar link <i>ru</i>            | \$ 97.10 X            |
| 102               |                                          | \$ 17,597.71          |
| Less 5%           |                                          | \$ 879.89             |
|                   |                                          | \$ 16,717.82          |

### SPECIAL NETT ITEMS

|   |                                                  |             |
|---|--------------------------------------------------|-------------|
| 1 | Front tyre <i>ru</i>                             | \$ 650.00 X |
| 1 | Front fender inner shield clip (1 set) <i>ru</i> | \$ 60.00 30 |
|   |                                                  | \$ 710.00   |

### LABOUR CHARGES

|     |                                               |                 |
|-----|-----------------------------------------------|-----------------|
| S/N | DESCRIPTION                                   | AMT(\$)         |
| 1   | To check wiring and reset headlamps focusing. | \$ 80.00 20     |
| 2   | To remove and refit front sensor.             | \$ 180.00 30    |
| 3   | To remove and refit front undercarriage.      | \$ 350.00 X     |
| 4   | To conduct wheel alignment.                   | \$ 180.00 60    |
| 5   | To apply undercoating.                        | \$ 150.00 30    |
| 6   | Panel beating.                                | \$ 1,500.00 300 |
| 7   | To re-spray painting on the affected areas.   | \$ 1,400.00 400 |
| 8   | To diagnose erase fault memory after repair.  | \$ 600.00 X     |
|     |                                               | \$ 4,440.00     |

GRAND TOTAL :

\$ 21,867.82

2-7032.27  
102  
6329.04  
30  
240  
7199.04