

29/7/24 F3237A

honda RS150R

- | | | |
|----------------------------------|-----------|------------|
| 1) front wheel shaft | 230 | cut — |
| 2) front wheel shaft nut | 10 | cut — |
| 3) front fork Assy | 2495 | Bent/m — |
| 4) steering cone bearing | 60 120 | Per — |
| 5) front signal (L) | 80 | cut — |
| 6) clutch lever | 30 | cut — |
| 7) handle balancer (L) | 25 | cut — |
| 8) side mirror (L) | 45 | cut — |
| 9) footrest complete (L) | 105 | cut — |
| 10) Rear signal (L) | 80 | cut — |
| 11) full cover set | (lot) 450 | cut — |
| 12) Tow | 45 | X |
| 13) labour | 400 | 300 |
| 14) front number plate | 20 | per 10 S/N |
| 15) position lamp LH & 75 cre | | ✓ |
| 16) position lamp cover & 80 cre | | ✓ |

(lot)
refer to 100

Not Authorised
means 9009660P

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) before resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

19/8/24
2 / S# 1350
3 days
wh phone the up ~

P-1565
102
1408.50
10
300
1718.50
202
1574