



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

INV No. AC2500124

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV Date 07/01/2025
Reference CD/LPC24080273/Kua3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLP 2648S
Insured Veh. GBE 5821P
Claim No. 24/24/24/VC05/029705
Policy No. Z24VC05021721
Accident Date 15/08/2024
Inspection Date 20/08/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LONPAC INSURANCE BHD	Ref:	CD/LPC24080273/Kua3q2
300 BEACH ROAD	Date:	07/01/2025
#17-04/07 THE CONCOURSE SINGAPORE 199555	Code:	LPC2

1. Policy Particulars :- DIRECT SETTLEMENT

Insured Veh.	GBE 5821P	Veh. Inspected	SLP 2648S
Policy No.	Z24VC05021721	Coverage	0
Claim No.	24/24/24/VC05/029705	Excess	\$0.00
Assign From	ERIC WOO	Assign Date	16/08/2024

2. Vehicle Details

Make & Model	MERCEDES BENZ E200 A	C.C	1991
Engine No.	27492030774792	Year of Reg.	30/05/2017
Chassis No.	WDD2130422A076883	Colour	METALLC PEARL WHITE
Odometer	128877 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	225/55R17	PIRELLI	7
L/H Front Tyre	225/55R17	PIRELLI	7
R/H Rear Tyre	225/55R17	PIRELLI	7
L/H Rear Tyre	225/55R17	PIRELLI	7

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	15/08/2024	Inspection Date	20/08/2024
Survey held at	KUM CHEW MOTOR WORKSHOP 160 SIN MING DRIVE #05-08 SIN MING AUTOCITY		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 3 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SLP 2648S

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER	BUCKLED	\$2,511.00	\$2,511.00
1	REAR BUMPER TOP RETAINER CENTRE	CRACKED	\$177.00	\$177.00
2	REAR BUMPER TOP RETAINER SIDE @\$56.00	CRACKED	\$112.00	\$112.00
2	REAR BUMPER LOWER BRACKET @\$85.00	SERVICEABLE	\$170.00	\$0.00
2	REAR FENDER RETAINER @\$133.00	SERVICEABLE	\$266.00	\$0.00
1	REAR BUMPER REINFORCEMENT	BENT	\$1,194.00	\$817.00
1	REAR BUMPER LOWER DIFFUSER	SERVICEABLE	\$447.00	\$0.00
1	REAR BUMPER LOWER DIFFUSER MOULDING	DENTED	\$462.00	\$342.00
16	REAR BUMPER RIVET @\$6.00	NECESSARY	\$96.00	\$96.00
8	REAR BUMPER CLIP @\$8.00	NECESSARY	\$64.00	\$64.00
2	REAR REVERSE SENSOR @\$213.00	SCRATCHED / SHORTED	\$426.00	\$426.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	\$2,276.00	\$0.00
	LESS 10.00% DISCOUNT		(\$820.10)	(\$454.50)
			\$7,380.90	\$4,090.50

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO PULL KNOCK ON ACCIDENT PORTION & REPLACE THE ABOVE PARTS.INCLUSIVE OF THE REPAIR OF REAR END PANEL.		\$380.00	\$350.00
	TO SPRAY PAINT ON REAR ACCIDENT PORTION		\$450.00	\$400.00
	TO ANTI-RUST REAR AFFECTED AREAS	NOT NECESSARY	\$150.00	\$0.00
	TO COLOUR PPF WRAP FOR REAR BUMPER.(ADDITIONAL)		\$600.00	\$600.00
			\$1,580.00	\$1,350.00

GRAND TOTAL			\$8,960.90	\$5,440.50
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			\$4,350.00

Report Ref No: CD/LPC24080273/Kua3q2

MARKET VALUE: \$95,000.00(EST) LESS LTA REBATE: \$51,791.00(EST) = NETT VALUE :\$43,209.00(EST)

KSC

KENNETH KONG SENG CHEONG



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SLP 2648S





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 2648S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SLP 2648S



PHOTOGRAPHS FOR VEHICLE NO. : SLP 2648S



PHOTOGRAPHS FOR VEHICLE NO. : SLP 2648S



PHOTOGRAPHS FOR VEHICLE NO. : SLP 2648S



PHOTOGRAPHS FOR VEHICLE NO. : SLP 2648S



PHOTOGRAPHS FOR VEHICLE NO. : SLP 2648S

