

SMRT Accident Vehicle Repair Estimates

	Section A - Accident Details				
Registration Number	SMB5890A				
Case Reference Number	BUS/06/24/5028				
Registration Date	10/12/2015				
Company Type	SMRT Buses Ltd				
Make	MAN				
Model	MAN A95				
Name of Driver	Yang Shuang				
Type of Accident	Side Swipe				
Accident Date and Time	6/21/2024 3:33 PM				
Accident Reported Date and Time	6/24/2024 10:15 AM				
Is Surveyor Required?	No				
Survey by					
Vehicle is Towed Back?	No				
Towed Back Date and Time					
Replacement Vehicle issued?	No				
Job Card Number	24122129				
Special Instruction to ARC,if any	SMB5890A - RIGHT FRONT PORTION SKZ2740S (TP) - INSURED WITH CHINA TAIPING				
Prepared Date and Time	8/16/2024 2:03 PM				
Chassis Number	WMAA95ZZ8F7002865				
Mileage					
Work Shop					
Repair Completion Date and Time					

Section B - Summary of Repair Estimates							
Summary of Repair Estimates							
	Quotation from ARC	Adjusted by Surveyor, if applicable					
Total Labour Cost	\$1,060.00	\$0.00					
Total Spray Cost	\$878.00	\$0.00					
Total Spare Part Cost	\$0.00	\$0.00					
Total Other Cost	\$0.00	\$0.00					
TOTAL COST	\$1,938.00	\$0.00					
Lump Sum Total	\$0.00	\$0.00					
Number of Repair Days	3.0						
Prepared / Adjusted By	ARC Manager Team						
ARC / Surveyor Sign Off Date	16/08/2024 2:04 PM						
Signature	×	×					
Remarks							

Section C - Quotation and Accident Invoice Details						
Quotation Number		Invoice Number				
Quotation Date		Invoice Date				
Invoice Amount		Prepared Date				

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 16/08/2024

User ID : choonhwee03



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

Date Generated : 16/08/2024

User ID : choonhwee03

			Secti	on D - Detai	ils of Repair E	stimates			
Part 1 - Labo	ur Works								
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REPAIR RH PORTION			\$1,060.00						
Total Labour			\$1,060.00						
Part 2 - Spray	/ Painting & Pa	anel Beating Rela	ted Works						
Job Scope			Quotation from ARC			Adjusted by Surveyor, if applicable			
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$878.00						
			\$878.00						
Part 3 - Other	Costs - Accid	lent and Accident	Repair Related Expens	se					
Job Scope			Quotation from ARC			Adjusted by Surveyor, if applicable			
Total Other Co	sts								
Part 4 - Spare	Parts / Materi	ial Usage							
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011052	BODY RH	20590172/2	BUMPER,CORNER:R/H, FOR ADL E500 DD BUS	1.00	\$1,181.40	100.00	\$0.00	Repair	
6011049	Body	20594593/2	DOME,FRONT PANEL:FOR ADL E500 DD BUS	1.00	\$7,732.80	100.00	\$0.00	Repair	
Total					\$8,914.20		\$0.00		
Added Spare	Parts / Materia	al Usage After Su	rveyor Signed off						
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check

Total