



SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/08/2024

User ID : choonhwee03

Section A - Accident Details	
Registration Number	SMB5890A
Case Reference Number	BUS/06/24/5028
Registration Date	10/12/2015
Company Type	SMRT Buses Ltd
Make	MAN
Model	MAN A95
Name of Driver	Yang Shuang
Type of Accident	Side Swipe
Accident Date and Time	6/21/2024 3:33 PM
Accident Reported Date and Time	6/24/2024 10:15 AM
Is Surveyor Required?	No
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24122129
Special Instruction to ARC,if any	SMB5890A - RIGHT FRONT PORTION SKZ2740S (TP) - INSURED WITH CHINA TAIPING
Prepared Date and Time	8/16/2024 2:03 PM
Chassis Number	WMAA95ZZ8F7002865
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$1,060.00	\$0.00
Total Spray Cost	\$878.00	\$0.00
Total Spare Part Cost	\$0.00	\$0.00
Total Other Cost	\$0.00	\$0.00
TOTAL COST	\$1,938.00	\$0.00
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	3.0	2 DAYS
Prepared / Adjusted By	ARC Manager Team	Taufikh
ARC / Surveyor Sign Off Date	16/08/2024 2:04 PM	16/8/24
Signature		
Remarks		Taufikh 97495749 WP 16/8/24 P/P RESURVEY AFTER REPAIR taufikh@LKKauto.com

Section C - Quotation and Accident Invoice Details			
Quotation Number		Invoice Number	
Quotation Date		Invoice Date	
Invoice Amount		Prepared Date	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SMRT Accident Vehicle Repair Estimates

SMRT Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 16/08/2024

User ID : choonhwee03

Section D - Details of Repair Estimates									
Part 1 - Labour Works									
Job Scope			Quotation from AR				Adjusted by Surveyor, if applicable		
TO REPAIR RH PORTION			\$1,060.00				530		
Total Labour			\$1,060.00						
Part 2 - Spray Painting & Panel Beating Related Works									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
PROVIDE LABOUR AND MATERIAL TO PUTTY AND RESPRAY ABOVE REPAIR ITEMS			\$878.00				708		
Total Spray Painting & Panel Beating			\$878.00						
Part 3 - Other Costs - Accident and Accident Repair Related Expense									
Job Scope			Quotation from ARC				Adjusted by Surveyor, if applicable		
Total Other Costs									
Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
6011052	BODY RH	20590172/2	BUMPER,CORNER:R/H, FOR ADL E500 DD BUS	1.00	\$1,181.40	100.00	\$0.00	Repair	XR
6011049	Body	20594593/2	DOME,FRONT PANEL:FOR ADL E500 DD BUS	1.00	\$7,732.80	100.00	\$0.00	Repair	XR
Total					\$8,914.20		\$0.00		
Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

530
708
\$1238
2 DAYS #